

Sub: Machine Tools & Operations	Code: 15ME45B
Date: 09 / 05 / 2017	Duration: 90 mins Max Marks: 50 Sem: IV Branch: MECH

Answer Any FIVE full Questions

Marks	OBE	
	CO	RBT
1 A) Describe different types of Tool motions in machining process [4]	CO2	L1
B) Briefly explain the desirable properties of cutting tool material [6]	CO3	L2
2 Derive the equations for the following machining parameters for turning operations spindle speed, cutting speed, cutting time, depth of cut, feed rate and material removal rate. [10]	CO2	L3
3 A mild steel bar of 63mm diameter and 200 mm long is to be turned to 60 mm diameter with the help of a HSS tool. Determine the cutting speed and time of machining if the approach length is set at 5mm and feed is set at 0.2mm/rev. [10]	CO2	L3
4 Estimate the time required to machine a cast iron surface 250 mm long and 150 mm wide on a shaper with cutting to return ratio of 3:2. Use a cutting speed of feed of 21mm/min, a feed of 2mm stroke and a clearance of 25 mm. the available ram strokes on the shaper are 28,40,60 & 90 strokes/min. also, determine MRR assuming depth of cut as 4mm. [10]	CO2	L3
5 A) Briefly explain the elements of single point tool with a neat sketch [6]	CO3	L2
B) Write short notes on the following cutting tool materials: (a) HSS (b) CBN [4]	CO3	L1
6 With a neat sketch, briefly explain the following for a single point cutting tool, (a) Back rake angle (b) End clearance angle (c) Side cutting edge angle (d) Nose radius [10]	CO3	L1
7 Derive the equations for the following machining parameters for slab milling operations spindle speed, cutting speed, cutting time, depth of cut, feed rate and material removal rate. [10]	CO2	L3

# Machine Tools & Operations

## Scheme of Evaluation

### Internal Assessment - 2

Sub code - 15ME45B

1)

A)

Definition of machine tool

Types of Tool motions

- 1) Primary motion or Cutting motion 2
- 2) Auxiliary motion 2

B)

Properties of cutting tool

- 1) Hot hardness 1
- 2) Toughness and impact strength 1
- 3) Coefficient of thermal expansion 1
- 4) Wear resistance. 1
- 5) Chemically stability 1
- 6) Cost 1

2).

- 1) Spindle speed - It is expressed in RPM and it is denoted by letter 'N'.

- 2) Cutting speed - It is the relative speed at which the tool passes through

the w/p material and removes the metal.  
It is expressed in m/min.

If  $V$  is the cutting speed,

$N$  is the spindle speed.

$D$  is the diameter of the w/p.

2

Then

$$V = \frac{\pi DN}{1000} \text{ m/min}$$

$$V = \frac{\pi N}{1000} \text{ mm/min.}$$

3) Cutting time ( $T_c$ )

It is the time taken to cut per pass and is denoted by ( $T_c$ )

If  $L$  is the length to be turned. 2

$$T_c = \frac{L}{fN} \text{ min.}$$

4) Depth of cut

It indicates how much the tool digs into the w/p during each pass and is denoted by letter  $f$ , and is measured in mm. 1

5) Feed Rate -

The relative speed at which the tool is linearly traversed over the w/p to remove the material. 1

### b) Material Removal Rate

It is the total volume of material being removed per unit time.

$$MRR = \text{cutting speed} \times f \times \text{depth of cut}$$

$$MRR = \pi D N f t \text{ mm}^3/\text{min.}$$

2

3)

Given

$$D_1 = 63 \text{ mm} \quad D_2 = 60 \text{ mm}$$

$$t = \frac{D_1 - D_2}{2} = \frac{63 - 60}{2} = 1.5 \text{ mm.}$$

$$\text{Length of job} = 200 \text{ mm} = L_j$$

$$f = 0.2 \text{ mm/rev}$$

$$\text{Length of approach} = 5 \text{ mm} = L_{app.}$$

$$\text{Let us assume. } \frac{\text{speed}}{\text{spindle speed}} = N = 200 \text{ rpm.}$$

Machining speed.

or

$$\text{Cutting speed} = V = \frac{\pi D N}{1000} \text{ m/min}$$

$$= \frac{\pi \times 63 \times 200}{1000}$$

5

$$V = 39.58 \text{ m/min}$$

$$\text{Cutting time} = T_c = \frac{L}{f N}$$

$$= \frac{L_j + L_{app}}{f N} = \frac{200 + 5}{0.2 \times 200}$$

5

$$= 5.125 \text{ min}$$

4)

Given

$$L_j = 250 \text{ mm}$$

$$b = 150 \text{ mm.}$$

$$m = \frac{2}{3} = 0.667$$

$$V = 21 \text{ m/min}$$

$$f = 2 \text{ mm/stroke.}$$

$$C = 25 \text{ mm}$$

$$t = 4 \text{ mm}$$

$$\text{Total length of stroke} = L_j + 2C.$$

$$= 250 + (2 + 25)$$

$$L = 300 \text{ mm.}$$

1

We, know

$$V = \frac{N_s L (1+m)}{1000}$$

$$\therefore N_s = \frac{V \times 1000}{L(1+m)} = \frac{21 \times 1000}{300(1+0.667)}$$

3

$$N_s = 41.9 \text{ strokes/min.}$$

$$\underline{\underline{N_s = 42 \text{ strokes/min}}}$$

Nearest available ram strokes is 40 strokes/min which is very near to the calculated value.

$$\Rightarrow \underline{\underline{N_s = 40 \text{ strokes/min}}}$$

Thus

$$\text{machining time } = T_c = \frac{b}{N_s f} \text{ min}$$

$$T_c = \frac{150}{40 \times 2}$$

$$\boxed{T_c = 1.875 \text{ min}}$$

3

## Material Removal Rate (MRR)

$$MRR = f \cdot N_s \cdot L (1+m)$$

$$= 2 \times 4 \times 40 \times 300 (1+0.667)$$

$$\underline{MRR = 160032 \text{ mm}^3/\text{min.}}$$


3

5)

- A) \* sketch of single point cutting tool

2

- \* Flank
- \* Heel
- \* Base
- \* Face
- \* cutting edges.



4

B)

- Brief explanation of HSS & CBN

2+2

6)

- \* 2D sketch of single point cutting tool

4


- \* Back rake angle



3

- \* End clearance angle

- \* Side cutting edge



3

- \* Nose radius

7)

## Slab milling parameters.

- 1) Spindle speed - Sp. Rotational motion of arbor and is denoted by letter 'N' is measured in rpm.
- 2) Cutting speed. - It is the linear velocity of any point on the periphery of the cutting edge. It is expressed in m/min.

$$V = \frac{\pi DN}{1000} \text{ m/min.}$$

where

D = dia. of w/p.

N = speed. of the spindle.

- 3) Feed Rate - It is the rate with which the w/p moves under the cutter while milling. It is expressed as mm/tooth of cutter ( $f_t$ ) or mm/rev of cutter ( $f_r$ ) or mm/min( $f_m$ ).

$$f_m = f_t \times Z \times N \text{ mm/min}$$

- 4) Depth of cut - It is the thickness of the metal removed from the w/p in one pass. of the cutter on the w/p. It is expressed in mm.

## Machining time.

It is the total time taken to mill a given surface on a w/p.

A milling cutter does not make a complete cut when it first comes in contact with the w/p.

$$T_m = \frac{L + L_A + C_1 + C_2}{f_m}$$

where

2

$L_A$  = length of tool approach

$C_1$  &  $C_2$  = clearance on both sides of the w/p.

$$L_A = \sqrt{t(D-t)}$$

## Material Removal Rate (MRR)

$$MRR = \frac{b \times t \times f_m}{1000} \text{ mm}^3/\text{min}$$

where

2

$b$  = width of cut, mm

$t$  = depth of cut, mm.

$f_m$  = feed rate mm/min.