

Internal Assessment Test –2

Sub: Mechanical Measurements & Metrology

Code: 15ME46B

Date: 08/05/2017

Duration: 90 mins

Max Marks: 50

Sem: IV

Branch (sections): ME (A & B)

Answer any FIVE FULL questions. Good luck!

Question paper with scheme & Solution		Marks	OBE	
			CO	RBT
1	What are comparators? Explain sigma comparator with neat sketch.	[10]		
Solu.	<p><b>Definition</b> – 2 Marks</p> <p><b><u>Sigma comparator</u></b></p> <p>sketch – 4 marks</p> <p>Explanation - 2 Marks</p> <p>Magnification formulae - 2 Marks</p>		CO3	L2
2	Explain how to measure width & depth of gear tooth using gear tooth vernier caliper.	[10]		
Solu.	<p>Sketch – 2 marks</p> <p>Measurement of width (w) – 4 Marks</p> <p>Measurement of depth (d) – 4 Marks</p>		CO4	L2
3	Explain LVDT & list the advantages & disadvantages of LVDT.	[10]		
Solu.	<p>Sketch – 3 Marks</p> <p>Cases 1, 2 &amp; 3 – 2 Marks each</p> <p>Output graph – 1 Mark</p>		CO3	L1
4	Explain measurement of effective diameter using 2 wire method.	[10]		
Solu.	<p>Sketch – 2 Marks</p> <p>Derivation for constant P – 4 Marks</p> <p>For Withworth thread – 2 Marks</p> <p>For Metric thread -2 Marks</p>		CO4	L2
5	Sketch and explain the following comparators:	[10]		
Solu.	<p>a) Zeiss Optimeter &amp; b) Solex Comparators</p> <p>a) Zeiss ultra optimeter</p> <p>Sketch – 3 Marks</p> <p>Explanation – 2 Marks</p> <p>b) Solex Comparators</p> <p>Sketch – 3 Marks</p> <p>Explanation – 2 Marks</p>		CO3	L3

6 What are Coordinate measuring machines? Explain any two types of CMM. [10]

Solu. Definition – 2 marks

Types –

Sketch – 2 marks each

Explanation – 2 Marks each

7 Explain i) alignment of gear tooth and ii) Parkinson gear tester with neat sketch. [10]

Solu. i) alignment of gear tooth  
2 types  
Analytical method – 2 Marks  
Functional method – 2 Marks

ii) Parkinson gear tester with neat sketch.  
Sketch – 3 Marks  
Explanation – 3 Marks

CO4	L2
CO4	L2

----- 0 -----

Q.1.

What are comparators? Explain sigma comparator with neat sketch.

soln:

A comparator is an instrument used for the measurement of diameters or lengths on gauges and components, using some standards.

The general principle of all these comparators is to indicate differences in size between the standard and the work being measured.

Sigma comparator:

Sigma comparator is an example of mechanical comparator with magnification in the range of 300 to 5000.




Figure:- Sigma comparator.

The plunger is attached to a rectangular bar which is supported at its upper and lower ends by flexure plates. A knife edge is fixed to the side of the rectangular bar which bears on a moving block.

The moving block and the fixed block are connected by flexible strips at right angles to each other.

If the external force is applied to the moving block, it would pivot about the line of intersection of the strip. This hinge is suitably pretensioned to allow it to ~~rotate~~ rotate within the range of the instrument scale. A fork arm or Y-arm attached to the moving block transmits rotary motion to the indicator driving drum through a bronze band wrapped around the drum.

magnification :-

If Y-arm is the length of the forked arm and 'x' is the distance from the knife edge to the hinge, then first magnification is  $Y/x$ .


If the pointer length is 'R' and radius of the drum is 'r', then the second stage magnification is  $R/r$ .

$$\therefore \underline{\underline{M = \frac{Y}{x} \times \frac{R}{r}}}$$

Q.2 Explain how to measure width and depth of gear tooth using gear tooth vernier calliper.

Soln:- Gear tooth vernier has two scale, horizontal and vertical scale.

The vertical vernier is used to set the depth 'd' along the pitch circle and horizontal vernier is used to measure width (w) at that point.




From sketch, width 'w' is therefore called chordal thickness and 'd' is called chordal addendum.

∴  $w = AB = 2AD$ .

We know that  $\theta = \frac{360^\circ}{4N}$

where N is the no. of teeth.

In the Δ<sup>o</sup> ADO,  $\sin \theta = \frac{AD}{AO}$



$AD = OA \sin \theta \Rightarrow w = 2AD = 2 \times AO \sin \theta$

$= 2R \sin \frac{360}{4N}$  (∵ R = pitch circle radius)

module  $m = \frac{\text{Pitch circle dia}}{\text{No. of teeth}} = \frac{2R}{N}$

∴  $R = \frac{Nm}{2}$

∴  $w = 2 \cdot \frac{Nm}{2} \cdot \sin\left(\frac{90}{N}\right)$

$w = Nm \sin\left(\frac{90}{N}\right)$

Also from the figure


$$d = a - OD.$$

Addendum is the radial distance from the pitch circle to the tip of the tooth, its value is equal to one module.

$$\begin{aligned} \therefore OC &= OE + \text{Addendum} = R + m. \\ &= \frac{Nm}{2} + m. \end{aligned}$$

From  $\Delta^{ic} ADO$ ,

$$OD = R \cos \theta$$



$$= \frac{Nm}{2} \cos\left(\frac{90}{N}\right)$$

$$\therefore d = \frac{Nm}{2} + m - \frac{Nm}{2} \cos\left(\frac{90}{N}\right)$$

$$d = \frac{Nm}{2} \left[ 1 + \frac{2}{N} - \cos\left(\frac{90}{N}\right) \right]$$

Q.3.

Explain LVDT & list the advantages and disadvantages

of LVDT.

Ans:-




Figure :- LVDT

It is an electro-mechanical device used to convert mechanical displacement into electrical signal.

It is a transformer consisting of 3 symmetrical spaced coils wound on an insulated column.

It works on the principle of mutual inductance and consists of 1 primary coil and 2 secondary coils.

Case 1: When the core is at null position, so for no displacement, the value of output  $e_o$  is zero as  $e_1$  and  $e_2$  both are equal.  
i.e.  $E_{sec1} - E_{sec2} = 0$ .

Case 2: When an external force is applied and if the steel core tends to move in the left hand direction (upwards) then the emf voltage induced in the secondary coil 1 is greater than secondary coil 2. So positive.  
 $\therefore E_{sec1} - E_{sec2}$  o/p.

Case 3: When an external force is applied and if the steel core moves in the right direction (downward) then the emf induced in the secondary coil 2 is greater compared to secondary coil 1.  
 $\therefore$  output voltage will be  $E_{sec2} - E_{sec1}$




Fig: LVDT'S AC output magnitude.

Q. 4. Explain measurement of effective diameter using 2 wire method.




Figure (i)




Figure (ii)

where E - Effective dia.

M - Dimension over the wires


T - Dimension under the wires.

Two wire method only two wires of required diameter will be placed on the screw thread to measure effective diameter.

Two wire method is used to determine the constant 'P'.  
T - dimension under the wire M - as from fig (i).

$P = 2 \cdot F_1$  by considering wire on both the sides.  
 $F_1 = E - T$  from figure (ii).

From  $\Delta^{ik} OAB$



$$\sin \theta/2 = \frac{OB}{OA}$$

$$OA = \frac{OB}{\sin \theta/2} \Rightarrow OB \operatorname{cosec} \theta/2$$


$$\therefore AG = OA - OG \text{ from figure (ii)}$$

$$= OB \operatorname{cosec} \theta/2 - r \quad (\because OG = OB = r)$$

$$= r \operatorname{cosec} \theta/2 - r = d/2 \operatorname{cosec} \theta/2 - d/2$$

$$AG = d/2 (\operatorname{cosec} \theta/2 - 1)$$

From  $\Delta^{ik} ADF$ ,  $\cot \theta/2 = \frac{AF}{DF}$





$$AF = DF \cot \theta/2$$

$$AF = \frac{P}{4} \cot \theta/2 \quad DF = P/4 \text{ from fig (ii)}$$

Considering wires on both the sides.

$$E - T = F_L$$

$$P = 2 \times F_L = 2 \times (AF - AD)$$

$$= 2 \left[ \frac{P}{4} \cot \theta/2 - d/2 (\operatorname{cosec} \theta/2 - 1) \right]$$

$$P = \frac{P}{2} \cot \theta/2 - d (\operatorname{cosec} \theta/2 - 1)$$

For Whitworth thread,  $\theta = 55^\circ$ .

$$P = \frac{P}{2} \cot (55/2) - d [\operatorname{cosec} (55/2) - 1]$$

$$P = 0.961P - 1.165d$$

For metric thread,

$$\theta = 60^\circ$$

$$P = \frac{P}{2} \cot (60/2) - d [\operatorname{cosec} (60/2) - 1]$$

$$\therefore P = 0.866P - d$$


Q.5. Sketch and explain the following comparators.

- a) Zeiss optimeter and b) Solix comparator.

Soln:- (a) Zeiss ultra-optimeter:

This is the optical system involves double reflection of light and thus gives higher degree of magnification.

Figure shows the details of zeiss optimeter.



A lamp sends light rays through green filter to filter all rays except green light, which causes less fatigue to eye. The green light then passes through a condenser which makes light rays parallel and pass through via index mark which projects to a movable mirror  $M_1$ . It is then reflected to another fixed mirror  $M_2$  and back again to the movable mirror. The objective lens brings the reflected beam from the movable mirror to a focus at a transparent graticule containing a precise scale which is viewed by the eyepiece. The plunger rests on the surface which has to be measured. If any deflection on the surface, it moves the plunger vertically which will tilt the mirror to some angle. This causes a shift in the position of the reflected index line on the eyepiece graticule scale, which in turn measure the displacement of the plunger.


(b) Solox pneumatic gauge :

Solox uses a water manometer for the indication of back pressure.

It consists of water tank in which water is filled upto a certain level and a dip tube is immersed into it upto a depth corresponding to the air pressure required. Since air is sent at high pressure than required, some air will escape from the dip tube and bubbles to the top of the water tank. Thus the air will moving in constant pressure through control orifice. The pressure in the manometer is regulated by the relative rates to escape of air through the control orifice and the measuring jets.

If the measuring jets are completely closed, the manometer level is depressed to the bottom of the tube.

The tube is graduated linearly to show changes in the pressures resulting from changes in the internal diameter of the work being measured.



Q.6.

What are coordinate measuring machines? Explain any two types CMM.

Q.6.1-

## Coordinate measuring machine [CMM]

CMM is a 3D device for measuring the physical geometrical characteristics of an object.

CMM is a specialised form of an industrial robot.

CMM include three main components

- main structure
- probing system and
- Data collection & reduction system.

## Types of CMM (any two types)

### i) Cantilever type :-

A vertical probe moves in the z axis carried by a cantilevered arm that moves in the y-axis.

This arm also moves laterally through the x-axis.




Figure: cantilever type

### Advantages:

- Large measuring range
- maximum accessibility.

Diso

Disadvantages:

- Bending of the cantilever above the measuring area.

Applications:


For checking sheet metal, cast iron and steel parts in the automotive industry, aircraft & ship building.

ii) Column type:

often referred to as universal measuring m/c instead of CMM.

The Column type CMM construction provides exceptional rigidity and accuracy.

These machines are usually reserved for gauge rooms rather than inspections.



Advantages:

- High accurations & speed
- low weight & large supporting base

Disadvantages:

- Suitable only for small measuring ranges
- only since the projecting part of the columns must have short length due to its rigidity

Applications:-

- In precision measurement on gauges & master parts.

Q.7.

Explain i) alignment of gear tooth and  
ii) parkinson gear tester with neat sketch.

Soln:-

i) Alignment of gear tooth:-

Alignment of each tooth on a gear is very essential otherwise the load will not be distributed evenly over its face.

Tooth alignment can be checked by placing a standard roller in the tooth space and checking for parallelism with a surface plate.

There are two methods to check alignment

- i) Analytical method
- ii) The functional method.

i) Analytical method:-

All the individual elements of the gear teeth are to be checked one by one.

This method is slow and tedious process

The analytical inspection of gears consists of determining the following elements one by one.

- i) profile
- ii) spacing
- iii) pitch
- iv) Run out or eccentricity or concentricity
- v) Thickness of tooth and
- vi) Backlash.

b) functional method :

carry out the running test of gear with another gear which is more accurate and it is known as control or master gear.

This method of inspection determines composite errors, vibration and noise.

<ii> Parkinson gear tester :

This test is commonly used in mass production of gear wheels. It takes much less time and gives quite accurate results.

The composite errors can be checked by measuring the variations of the centre distance when the gear to be tested is rotated under spring pressure against a master gear. The test is generally performed on a most commonly used machine called parkinson gear tester.





Figure :- Parkinson gear tester :

If the gear to be tested and master gear rotate manually if their any deviations b/w the gears i.e. variations in the centre distance the calibrated spring helps to move the movable carriage show that deviation will be noted in the dial indicator

If the gear under test and master gear rotates automatically then there will be a electronic sensor which reads the variation b/w the centre distance and gives the out put on a wax paper like a trace.




(i)

Fully Satisfactory



(ii) moderate



(iii) Rejected (not satisfactory)