

USN	
-----	--

**Subject:** **RAPID PROTOTYPING**

**Date:** \_\_\_\_\_ **Duration:** 90mins **Max Marks:** 50 **Sem:** **VIII**

**Code:** 10ME837

**Section:** A & B

**Note: Answer any 5 questions (5 x 10 = 50)**

- Compare Indirect and Direct Rapid tooling.
  - Describe the steps involved in producing silicon rubber tooling.
- Briefly explain the 3Q Keltool process and list out the materials used.
- Briefly classify the direct methods for Rapid Tool production.
- With a neat sketch, explain the Quick cast process.

OBE	
CO	RBT
[4]	
[6]	CO3 L2
[10]	CO3 L2
[10]	CO3 L1
[10]	CO3 L1

USN	
-----	--

**Subject:** **RAPID PROTOTYPING**

**Date:** \_\_\_\_\_ **Duration:** 90mins **Max Marks:** 50 **Sem:** **VIII**

**Code:** 10ME837

**Section:** A & B

**Note: Answer any 5 questions (5 x 10 = 50)**

- Compare Indirect and Direct Rapid tooling.
  - Describe the steps involved in producing silicon rubber tooling .
- Briefly explain the 3Q Keltool process and list out the materials used.
- Briefly classify the direct methods for Rapid Tool production.
- With a neat sketch, explain the Quick cast process.

OBE	
CO	RBT
[4]	
[6]	CO3 L2
[10]	CO3 L2
[10]	CO3 L1
[10]	CO3 L1

Solution Key Cum Scheme of Evaluation

academic year: 2016-17

Branch: B.E / Mechanical

subject code: 10ME837

Semester: 8

subject: Rapid Prototyping.

C.I: Prof. H. Mamtandan

Solution	Marks.
<p>Indirect rapid tooling or Hard tooling are fabricated by machining either tool steel or aluminium into negative shape of the desired component.</p> <p>Direct rapid tooling or soft tooling can be used to initiate multiple wax (or) plastic parts using conventional injection moulding techniques.</p> <p><u>Silicon Rubber Tooling</u></p> <p>Steps</p> <ol style="list-style-type: none"> <li>1: Producing any pattern using RP methods.</li> <li>2: Adding <sup>venting</sup> &amp; Gating to the pattern.</li> <li>3: Setting up the pattern in a mould box.</li> <li>4: Pouring Silicon rubber to form one-half of the mould.</li> <li>5: Inverting one half of the mould &amp; removing the plasticine.</li> <li>6: Pouring Silicon rubber to produce second half of the mould.</li> </ol> <p><u>3D Kel tool</u></p> <p>Based on metal sintering process.</p> <p><u>Steps involved</u></p> <p>→ Fabricating master patterns of core f</p>	<p>4</p> <p>6</p>

Q. NO

Solution

- Producing RTM silicone rubber moulds
- Filling Silicon Rubber moulds with metal mixtures.
- Firing Green parts in the furnace
- Infiltrating sintered parts.
- Finishing core of cavity.

Materials used

- Steelite.
- Al Composite tool steel.

8

2

3) Direct methods of RP Tool production

can be classified into

- a) Form Tooling
- b) Hard Tooling.

Form Tooling

- 1) Direct AIM
- 2) DTM Copper PA Tooling
- 3) LOM Tooling in Polymer
- 4) 3DP Ceramic shells.
- 5) DTM Sand form Tooling

Hard Tooling

- EOS Direct Tool.
- DTM Rapid Tool Process
- LOM Tooling in Ceramic
- 3DP Direct metal tooling

2

8

4) Quick cast process

Quick cast- pattern sketch

This process replaces traditional wax patterns for investment casting with SLA patterns.

Process description

→ A stereolithography Quick cast pattern is created from an STL file.

→ Pattern is leak tested, to make sure it is air tight.

→ An investment Caster is chosen.

→ Quick cast pattern is given to the Caster

→ Caster cuts part through ceramic coating process & performs firing procedures to burn out SLA pattern.

→ Metal is poured into the fired ceramic shell.

→ Ceramic shell is broken off to reveal metal part.

5) Data preparation errors in RP

(i) Errors due to tessellation

a) Chord height

b) Angle control.

(ii) Errors due to slicing.

(i) Errors due to tessellation

A STL file approximates the surface of 3D CAD model by triangles.

3

4

6

- Producing RTM silicone rubber moulds
- Filling Silicon Rubber moulds with metal mixtures.
- Firing Green parts in the furnace
- Infiltrating sintered parts.
- Finishing core of cavity.

Materials used

- Stellite.
- Al Composite tool steel.

3) Direct Methods of RP Tool Production

Can be classified into

- a) Firm Tooling
- b) Hand Tooling.

<u>Firm Tooling</u>	<u>Hand Tooling</u>
<ol style="list-style-type: none"> <li>1) Direct AIM</li> <li>2) DTM Copper PA Tooling</li> <li>3) LOM Tooling in Polymer</li> <li>4) 3DP Ceramic shells.</li> <li>5) DTM Sand form Tooling</li> </ol>	<ul style="list-style-type: none"> <li>EOS Direct-Tool.</li> <li>DTM Rapid Tool process</li> <li>LOM Tooling in Ceramic</li> <li>3DP Direct metal tooling</li> </ul>

Q.No	Solution	Marks
4)	<p><u>Quick cast process</u></p> <p>Quick cast- pattern sketch</p> <p>This process replaces traditional wax patterns for investment casting with SLA patterns.</p> <p><u>Process description</u></p> <ul style="list-style-type: none"> <li>→ A stereolithography Quick cast pattern is created from an STL file.</li> <li>→ Pattern is leak tested, to make sure it is air tight.</li> <li>→ An investment Caster is chosen.</li> <li>→ Quick cast pattern is given to the Caster</li> <li>→ Caster cuts part through ceramic coating process &amp; performs firing procedures to burn out SLA pattern.</li> <li>→ Metal is poured into the fired ceramic shell.</li> <li>→ Ceramic shell is broken off to reveal metal part.</li> </ul>	4
5)	<p><u>Data preparation errors in RP</u></p> <ul style="list-style-type: none"> <li>(i) Errors due to tessellation           <ul style="list-style-type: none"> <li>a) Chord height</li> <li>b) Angle control.</li> </ul> </li> <li>(ii) Errors due to slicing.</li> </ul> <p><u>(i) Errors due to tessellation</u></p> <p>A STL file approximates the surface of 3D CAD model by triangles.</p>	6

(3)

## Chord height

This parameter specifies the maximum distance between a chord & surface. If less deviation from the actual part surface is required, a smaller chord height is required.




Fig : Chord height.

## Angle Control

This parameter specifies the required definition level along curves with small radius.

$$r < r_0 = \frac{\text{Part size}}{10}$$

## Errors due to slicing.

→ RP processes have a stair-stepping problem that is found in all layer manufacturing technologies. Stair stepping is a consequence of the addition of material in layers.

→ There are 2 types of errors resulting from slicing. One is because of mismatching in height b/w slice positions and feature boundaries; the other is the replacement of polygons with stair steps.

6a) Factors influencing accuracy of RP processes ..

- Errors during data preparation stage such as STL file generation, model slicing & part build direction.
- Process specific parameters during the build stage; which influences accuracy of part.
- Part finishing techniques employed.

5

6b) Part building errors in SL Process.

- Curing errors
- Contrast errors

Curing Errors

- a) Over curing
- b) Scanned line shape.

\* Over curing results in unusual thickness which causes a dimensional change in the Z direction along the lower feature boundary.

\* A scanned line is created when a laser beam scans the resin surface. The C.S of the scanned line is referred to as the scanned line shape.

(5)



(5)