

Internal Assessment Test –II

| | | | |
|--|---|------------|-----------------|
| Sub: | Electric Machine Design (EMD) | Code: | 15EE64 |
| Date: | 20/04/2019 | Duration: | 90 mins |
| | | Max Marks: | 50 |
| | | Sem: | 6 th |
| | | Branch: | EEE |
| Answer any 5 questions from remaining. Sketch figures wherever necessary. | | | |
| | | | Marks |
| | | | OBE |
| | | | CO Level |
| Q1(a) | Explain procedure to determine the no load current of transformer with relevant expression. | [05] | CO5 L2 |
| Q1(b) | A 400 kVA, 6600 V/400 V, 50 Hz, delta-star, 3- ϕ , core type transformer has the following data: width of HV winding=35mm, width of LV winding=26 mm, Height of coils is 0.8 m, length of mean turn=1.0 m, HV winding turns=960, width of duct between LV and HV winding=20 mm. Calculate leakage reactance of the transformer referred to HV side. | [05] | CO5 L3 |
| Q2 | List the factors to be considered during the selection of number of poles in DC machines. | [10] | CO4 L1 |
| Q3 | Obtain an expression for the leakage reactance of a transformer with primary and secondary coils of equal length. | [10] | CO5 L3 |
| Q4 | A 300 kVA 11000/440 V, 50Hz, 3- ϕ , delta/star, core type oil immersed, self-cooled transformer gave the following results during design calculations of magnetic frame and windings centre to centre distance of cores=36 cm, height of window= 44 cm, height of yoke 17 cm, total weight of magnetic frame =700 kg, average specific iron loss =2.1 W/kg, outer dia of HV winding=35 cm, resistance of LV winding per phase = 0.0047 Ω , resistance of HV winding per phase = 9.74 Ω . Calculate i. Dimensions of tank with clearance of $\Delta L=8$ cm, $\Delta W=10$ cm, $\Delta H= 45$ cm ii. Number of cooling tubes if temperature rise not to exceed 35°C. Assume diameter of cooling tubes as 5 cm and length of cooling tube =95 cm | [10] | CO5 L3 |
| Q5 | A single phase, 50 Hz oil cooled core type transformer is built from stampings having a relative permeability of 1000. Length of flux path is 3 m, area of cross section of core is 2.25×10^{-3} m ² and primary winding has 800 turns. Estimate the maximum flux density and no load current of the transformer. Given loss at working flux density is 2.6 w/kg, weighs 7.8×10^3 kg/m ³ , stacking factor=0.9. | [10] | CO5 L3 |
| Q6 | Determine the main dimensions, number of poles, number of armature conductors, number of slots, conductors per slot and size of armature conductor for a 250 kW, 400 V, 625 A, 600 rpm, lap wound compound generator, assuming following data: average flux density =0.63 T; specific electric loading= 33000 ampere conductors/m, field and armature copper loss = 5 % of output; ratio of pole arc to pole pitch=0.7; pole arc= gross length of armature. Armature drop=3 % of terminal voltage, current density $\delta= 5$ A/mm ² ; slot pitch =2.6 cm. | [10] | CO4 L3 |
| Q7 a | From first principles derive output equation of DC Machine. | [04] | CO2 L4 |
| Q7 b | Define specific magnetic loading and specific electrical loading. Also mention the advantages of choice of higher values of specific loadings in the design of any machine. | [06] | CO3 L1 |

Solution

Q1. (a)

To find No-load current:-

No load current $\left[\begin{array}{l} \text{magnetizing current } (I_m) \\ \text{loss component current } (I_c) \end{array} \right]$

So, $I_0 = \sqrt{(I_m)^2 + (I_c)^2}$

To find I_m i.e magnetizing current.

$I_m = \frac{AT_0}{\sqrt{2} T_p}$ AT_0 - ampere turns at No load
 T_p - No. of turns in primary.

* Check whether ' T_p ' is given, if Not Calculate T_p using 'emf equation'

$E_p = 4.44 f \phi_m T_p$ $\phi_m = B_m A_i$

A_i - Net iron area (m^2)
 A_g - Gross iron area (m^2) $A_i = A_g \times \text{stacking factor (usually 0.9)}$
 B_m - max. flux density (w/m^2)
 (T) Gross iron area.

Now Question is how to find ' AT_0 '

There are many ways to find ' AT_0 '

① If permeability is mention in Question (μ_r)

$AT_0 = \text{reluctance} \times \text{flux}$

$AT_0 = \frac{l_i}{\mu_0 \mu_r A_i} \times \phi_m$

here
 $\mu_0 = 4\pi \times 10^{-7}$
 μ_r - relative permeability

Then find (ϕ_m)

A_i - gross iron area
 $A_i = 2(A_c + A_y) - 1\phi \times m_e$
 $A_i = 3(A_c) + 2A_y - 3\phi \times m_e$

② If at/m is mentioned for total iron area then

$AT_0 = at/m \times l_i + \text{mmf at joints}$

mmf at joints

$AT_g = 2.0 \times 10^5 B_g l_g$

l_g - length of air gap

B_g - flux density of air gap

$B_g = \frac{B_{av}}{\psi}$

③ If at/m is mentioned separately then it's different for different type of x^{mer}

core type

① 1ϕ x^{mer} - $AT_0 = 2(l_{tc} * l_c) + 2(l_{ty} * l_y)$ + mmf for joints

② 3ϕ x^{mer} - $AT_0 = 3(l_{tc} * l_c) + 2(l_{ty} * l_y)$ + mmf for joints

Shell type - ① 1ϕ x^{mer} $AT_0 = 2l_{tc} * l_c + 2(l_{ty} * l_y)$ + mmf for joints

* For a 3ϕ x^{mer} $AT_0 / \text{phase} = \frac{AT_0}{3}$

So magnetizing current / phase

$$I_m = \frac{AT_0}{\sqrt{2} T_p}$$

→ This is magnetizing current / phase if AT_0 is ampere turns / phase

or else

$$\frac{AT_0}{\sqrt{2} T_p} = I_m$$

→ Total magnetizing current if AT_0 is ampere turns total.

To find ' I_c ' i.e. Core loss Component

$$I_c = \frac{\text{Iron losses}}{\text{Voltage (Primary)}}$$

Iron losses will not be directly mentioned in watts. so we have to calculate Iron losses in watts

Iron losses/kg will be mentioned.
 so we need to find weight of iron

$$\text{Weight} = \text{Volume} \times \text{density of iron}$$

$$\text{Volume} = \text{Area of iron} \times \text{length of iron path}$$

$$(A_i) \quad (l_i)$$

* length of iron can be directly mentioned in question * or you need to calculate.

$$1\phi \text{ x mer} - l_i = 2l_c + 2l_y$$

$$3\phi \text{ x mer} - l_i = 3l_c + 2l_y$$

* Area of iron can be given in question or you have to calculate *

We can calculate using emf equation

$$E_p = 4.44 f B_m A_i T_p$$

Then finally calculate $I_o = \sqrt{I_c^2 + I_m^2}$

Q1.b1

1 b)

Given

$$400 \text{ KVA}$$

$$b_p = 35 \text{ mm} = 0.035 \text{ m}$$

$$b_s = 26 \text{ mm} = 0.026 \text{ m}$$

$$l_c = 0.8 \text{ m}$$

$$l_{mt} = 1 \text{ m}$$

$$T_p = 960$$

$$a = 20 \text{ mm} = 0.02$$

$$X_L = 2\pi f \mu_0 T_p^2 \frac{l_{mt}}{l_c} \left[\frac{b_s + b_p}{3} + a \right]$$

$$= 2\pi (50) (4\pi \times 10^{-7}) (960)^2 \times \frac{1}{0.8} \left[\frac{0.035 + 0.026}{3} + 0.02 \right]$$

$$= 2 \times \pi \times 50 \times (4\pi \times 10^{-7}) (960)^2 \times \frac{1}{0.8} \left[\frac{0.035 + 0.026}{3} + 0.02 \right]$$

$$X_L = 454.79 (0.04)$$


$$X_L = 18.34 \Omega$$

Q2.

Factors affecting no of poles

1. Frequency: - The frequency of flux reversal $f = \frac{Pn}{2}$
 So if $P \uparrow$ $f \uparrow$. Higher f leads to iron losses
 in armature teeth & core. $f \rightarrow 25-50\text{Hz}$.

2. Weight of iron parts: - i) Yoke area - Flux/pole in
 2 pole machine is $\frac{\phi_T}{2}$ and that
 in yoke $\frac{\phi_T}{4}$
 → 4 pole machine is $\frac{\phi_T}{4}$ & in yoke
 $\frac{\phi_T}{8}$



So concluding flux in yoke
 is inversely proportional to
 no. of poles so all
 poles increases flux carried
 by yoke decreases thus reducing area of yoke.

ii) Armature core area: - flux/pole in armature
 core in 2 pole machine $\frac{\phi_T}{4}$ 4 pole $\Rightarrow \frac{\phi_T}{8}$

flux reversal happens in armature core so
 increase in poles will increase iron losses

$B_c \rightarrow$ flux density in armature core
 $f \rightarrow$ frequency of flux reversals
 $n \rightarrow$ speed in rps

2 pole m/c.

$$\text{eddy current loss} \propto B_c^2 f^2$$

$$\propto B_c^2 \left(\frac{Pn}{2}\right)^2$$

$$\propto B_c^2 \frac{P^2 n^2}{4}$$

$$\propto \left(\frac{\phi_T}{4A_2}\right)^2 \frac{P^2 n^2}{4}$$

$$\propto \frac{\phi_T^2}{16} \frac{1}{A_2^2} \frac{4n^2}{4}$$

$$\propto \frac{\phi_T^2 n^2}{16 A_2^2}$$

4 pole m/c

$$\text{eddy current loss} \propto B_c^2 f^2$$

$$\propto B_c^2 \left(\frac{Pn}{2}\right)^2$$

$$\propto \left(\frac{\phi_T}{8A_4}\right)^2 \left(\frac{4n}{2}\right)^2$$

$$\propto \frac{\phi_T^2 4n^2}{64 A_4^2}$$

$$\propto \frac{\phi_T^2 n^2}{16 A_4^2}$$

Hysteresis loss

$$2 \text{ pole} \rightarrow B_c^2 f = \left(\frac{\phi_T}{4A_2}\right)^2 \frac{pn}{2} = \frac{\phi_T^2 n}{16A_2^2}$$

$$4 \text{ pole} \rightarrow B_c^2 f = \left(\frac{\phi_T}{8A_2}\right)^2 \frac{pn}{2} = \frac{\phi_T^2 2n}{64A_2^2} = \frac{\phi_T^2 n}{32A_2^2}$$

The hysteresis loss is reduced by 50%.

eddy current loss remains same with increase

in poles

Hysteresis loss is inversely proportional.

③ overall diameter: $\frac{\text{Total armature mmf}}{\text{Total field mmf}} = \frac{1}{K}$

$$\text{Total field mmf} = \frac{K(Ac)}{2}$$

$$\frac{\text{mmf}}{\text{pole}} = \frac{K(Ac)}{2P}$$

So as it is inversely proportional to pole

as pole \uparrow mmf \downarrow so pole height \downarrow reason.

So overall diameter decreases as pole \uparrow

3. Weight of Copper


Armature Copper: active part
inactive part

The inactive part must be less to make the machine cheaper.

as the diameter of machine remains same if no. of poles increases the pole pitch decreases thus decreasing the overhang



(inactive part of machine) length, so this will reduce the copper & overall length of machine



So increase in number of poles reduces weight of copper and also overall length of machine is reduced.

⑥ Field copper: As we have previously seen the field mmf is inversely proportional to poles, for two poles the area of cross-section of each pole is more, while that of 4 pole is less, so the total field copper decreases with increase in number of poles, as increase in pole number decreases the pole height also.

So increase in number of poles decreases both armature & field winding copper.

4. length of commutator: - Wave wound $A=2$
Lap wound $A=P$

2 pole m/c: Current/parallel path $I_b = \frac{I_a}{2}$ (C.P)

$$I_b = 2 I_a = I_a$$

4 pole m/c: $I_b = \frac{I_a}{4}$ $I_b = 2 I_a = \frac{I_a}{2}$

So current collected per brush = $\frac{I_a}{\text{No. of brushes}}$
 No. of brushes = $\frac{\text{No. of parallel paths (Poles)}}{\text{lap}}$

So length and thickness of each brush will increase decrease as poles increases thus it also reduces the length of commutator thus reduces over all length of ~~the~~ machine

5) Labour charges :- a) Armature coils -

No. of armature coils increases with no. of armature conductors
 So No. of coils \propto with no. of poles.

$$E = \frac{P \phi Z N}{60 A}$$

$$E \propto \frac{N Z}{A}$$

So No. of commutator segments = no. of coils
 So commutator \uparrow with poles \uparrow

Lap $E \propto \frac{N Z}{P}$
 Wave $E \propto N Z$
 $Z \propto \frac{P E}{N}$
 Poles are independent of poles

b) Field coils - It is equal to No. of poles
 So field coils to be assembled is higher with higher no. of poles

So labour charges will increase with no. of poles

6) Flash over :- Brush arms \uparrow with no. of poles
 So for the same diameter of commutator no. of brushes will increase. So the distance between brushes decreases so to reduce flashover the diameter of commutator has to be increased if poles \uparrow .

7) Distortion of field :-

Armature mmf/poles $A_T a = \frac{a_c}{c} \times \text{pole pitch}$
 A armature mmf/pole is inversely proportional to poles, so smaller no. of poles will lead to more mmf/pole which will increase the distortion of field, sparking etc. So less no. of poles is not preferable.

Q3.

Expression for leakage reactance of Core type transformer with Concentric Coils.


Assumptions

- * axial length of primary & secondary are same
- * length of mean turn of windings are equal
- * Flux path are parallel to windings in axial length
- * Mmf required for iron parts is negligible
- * So magnetizing current is negligible

$$AT = I_p T_p = I_s T_s$$

- * reluctance of flux path through Yokes is negligible
- * Half of leakage flux in duct links with each winding
- * Windings are uniformly distributed \therefore mmf varies linearly from zero to AT

- ϕ_p - leakage flux in primary
- ϕ_s - leakage flux in secondary
- ϕ_0 - flux through duct.
- L_c - mean circumference of duct
- L_w - axial length of windings.
- b_p, b_s - radial width of primary & secondary windings.
- a - width of duct.



$$\text{mmf across strip} = I_p T_p \frac{\chi}{b_p}$$

$$\text{Permeance of strip} = \frac{\mu_0 L m t p dx}{L_c}$$

$$\therefore \text{Flux in strip} = \text{mmf} \times \text{Permeance}$$

$$= I_p T_p \frac{\chi}{b_p} \times \frac{\mu_0 L m t p dx}{L_c}$$

$$= \mu_0 \frac{L m t p}{L_c} I_p T_p \frac{\chi}{b_p} dx$$

Flux links with $\frac{\chi}{b_p} T_p$ turns

$$\therefore d\psi_1 = \mu_0 \frac{L m t p}{L_c} I_p T_p \frac{\chi}{b_p} dx \cdot \frac{\chi}{b_p} T_p$$

$$d\psi_1 = \mu_0 \frac{L m t}{L_c} I_p T_p^2 \frac{\chi^2}{b_p^2} dx$$

$$\psi_1 = \mu_0 \frac{L m t}{L_c} I_p T_p^2 \int \chi^2 dx$$

$$\psi_1 = \mu_0 \frac{L m t}{L_c} I_p T_p^2 \left[\frac{\chi^3}{3} \right]_0^{b_p}$$

$$\psi_1 = \mu_0 \frac{L m t}{L_c} I_p T_p^2 \left[\frac{b_p^3}{3} \right]$$

$$\psi_1 = \mu_0 \frac{L m t p}{L_c} I_p T_p^2 \cdot \frac{b_p}{3}$$

Duct portion

$$\text{mmf across duct} = I_p T_p$$

$$\text{Permeance of duct} = \frac{\mu_0 L_0 a}{L_c}$$

$$\text{flux in duct } \phi_0 = I_p T_p \times \frac{\mu_0 L_0 a}{L_c}$$

Half of the flux links with each winding

$$\text{So flux in primary winding } \phi_0 = \frac{1}{2} I_p T_p \times \frac{\mu_0 L_0 a}{L_c}$$

$$\text{So flux linkages } \psi_0 = \frac{1}{2} I_p T_p \mu_0 \frac{L_0 a}{L_c} \times T_p$$

Hence total flux linkages

$$\psi_p = \psi_1 + \psi_0$$

$$= \mu_0 \frac{L m t p}{L_c} I_p T_p^2 \cdot \frac{b_p}{3} + \frac{1}{2} I_p T_p \mu_0 \frac{L_0 a}{L_c} T_p$$

$$= \frac{\mu_0 I_p T_p^2}{L_c} \left(L m t p \frac{b_p}{3} + \frac{L_0 a}{2} \right)$$

$$\psi_p = \mu_0 I_p T_p^2 \frac{L m t p}{L_c} \left(\frac{b_p}{3} + \frac{a}{2} \right)$$

(Consider $L m t p = L_c = L m t$)

$$\text{Leakage inductance of primary wdg} = \frac{\psi_p}{I_p} = \frac{\mu_0 T_p^2 L m t p}{L_c} \left(\frac{b_p}{3} + \frac{a}{2} \right)$$

Leakage reactance

$$\chi_p = 2\pi f L$$

$$\chi_p = 2\pi f \left(\mu_0 T_p^2 \frac{L m t p}{L_c} \left(\frac{b_p}{3} + \frac{a}{2} \right) \right)$$

Similarly

$$\chi_s = 2\pi f \left(\mu_0 T_s^2 \frac{L m t}{L_c} \left(\frac{b_s}{3} + \frac{a}{2} \right) \right)$$

Leakage reactance of secondary referred to primary

$$\chi_s' = \chi_s \left(\frac{T_p}{T_s} \right)^2$$

$$= 2\pi f \mu_0 T_p^2 \frac{L m t}{L_c} \left(\frac{b_s}{3} + \frac{a}{2} \right)$$

$$\chi_p = \chi_p + \chi_s'$$

$$= 2\pi f \mu_0 T_p^2 \frac{L m t}{L_c} \left[\frac{b_s}{3} + \frac{a}{2} + \frac{b_p}{3} + \frac{a}{2} \right]$$

$$\chi_p = 2\pi f \mu_0 T_p^2 \frac{L m t}{L_c} \left[\frac{b_s + b_p}{3} + a \right]$$


Leakage reactance in pu

$$E_{\chi} = \frac{\chi_p}{(V_p/I_p)} = \frac{2\pi f \mu_0 I_p T_p^2}{V_p} \frac{L m t}{L_c} \left[\frac{b_s + b_p}{3} + a \right]$$

Q4.

Given

- D = 36 cm
- Hw = 44 cm
- Ht = 17 cm
- Weight = 700 kg
- $P_i = 2.14 \text{ W/kg}$
- de = 35 cm
- $R_{LW} = 0.0047 \Omega = R_s$
- $R_{HV} = 9.74 = R_p$
- $\Delta L_s = 8 \text{ cm}$
- $\Delta W = 10 \text{ cm}$
- $\Delta h = 45 \text{ cm}$



① Dimensions of tank

① $L_t = L + \Delta L_s$

$= 44 \times 10^{-2} + 8 \times 10^{-2}$

$L_t = 0.52 \text{ m}$

② $W_t = W + \Delta W$

$= 2D + de + \Delta W$

$= 2(36 \times 10^{-2}) + (35 \times 10^{-2}) + 10 \times 10^{-2}$

$W_t = 1.17 \text{ m}$

③ $H_t = H + \Delta h$

$= H_w + 2H_t + \Delta h$

$= 44 \times 10^{-2} + 2(17 \times 10^{-2}) + 45 \times 10^{-2}$

$H_t = 1.23 \text{ m}$

heat dissipated by tank = 1400 st

$\theta = \frac{3003.11}{12.5 \times 4.15}$

$\theta = 57.78^\circ \text{C}$

$S_t = 2H_t(W_t + L_t)$
 $= 2 \times 1.23(1.17 + 0.52)$

$S_t = 4.15 \text{ m}^2$

③ No. of cooling tubes.

$\theta = 35^\circ \text{C}$

Surface area of tube = χS_t

$\theta = \frac{P_{loss}}{(12.5 + 8.8 \chi) S_t}$

$35 = \frac{3003.11}{(12.5 + 8.8 \chi)(4.15)}$

$8.8 \chi = \frac{3003.11}{35 \times 4.15} - 12.5$

$\chi = 0.929$

Area of tube = $\pi d_{tu} l_{tu}$

$= \pi \times 5 \times 10^{-2} \times 95 \times 10^{-2}$
 $= 0.15 \text{ m}^2$

$d_{tu} = 5 \times 10^{-2} \text{ m}$
 $l_{tu} = 95 \times 10^{-2} \text{ m}$

$n_t = \frac{\chi S_t}{A_{tu}} = \frac{0.929 \times (4.15)}{0.15}$

$n_t = 25.8$ $n_t = 26$

② Temp rise of plain tank

$P_i = 2.1 \times 700$ ($\therefore P_i = \text{kg} \times \text{weight}$)
 $P_i = 1470 \text{ W}$

$P_{cu} = I^2 R$
 $= I_p^2 R_p + I_s^2 R_s$

$I_p = \frac{300 \times 10^3}{11000}$

$I_{phP} = \frac{I_p}{\sqrt{3}} = 15.74 \text{ A}$

As it is delta on primary

$V_{ph} = V_L = 11000$

$I_p = \frac{300 \times 10^3}{3 \times 11000}$

$I_p = 9.09 \text{ A}$

As it is star on secondary

$V_{ph} = \frac{V_L}{\sqrt{3}} = \frac{440}{\sqrt{3}} = 254.03 \text{ V}$

$I_s = \frac{300 \times 10^3}{3 \times 254.03} = 393.65 \text{ A}$

$P_{cu} = (9.09)^2 (9.74) + (393.65)^2 (0.0047)$

$P_{cu} = 1533.11 \text{ W}$

$P_{loss} = P_i + P_{cu} = 1470 + 1533.11 = 3003.11 \text{ W}$

$\theta = \frac{P_{loss}}{\text{Heat dissipated by tank}}$

Q5.

1) $f = 50 \text{ Hz}$

$N = 1000$

$W_t = 3 \text{ m}$

$A_p = 2.25 \times 10^3 \text{ m}^2$

$T_p = 800$

$P_i = 2.6 \text{ W/kg}$

Weight = $7.8 \times 10^3 \text{ kg/m}^3$

Stacking factor = 0.9

$V = 400 \text{ V}$

$P_i = 2.6 \text{ W/kg}$

Weight \times Volume = $7.8 \times 10^3 \times A_p \times L_t$
(kg/m^3) (m^3) = $7.8 \times 10^3 \times 2.25 \times 10^3 \times 3$
 $= 52.65 \times 10^6 \text{ kg}$

Iron loss = 2.6×52.65
 $= 136.89 \text{ W}$

$I_c = \frac{P_i}{V}$
 $= \frac{136.89}{400}$

$I_c = 0.34 \text{ A}$

$$I_u = \frac{AT_0}{\sqrt{2} T_P}$$

$$AT_0 = \text{reluctance} \times \text{flux}$$

$$= \frac{L^2}{\mu_0 \mu_r A^2} \times \phi_m$$

$$= \frac{3}{4\pi \times 10^{-7} \times 1000 \times 2.25 \times 10^{-3}} \times B_m A^2$$

$$= \frac{3 \times 1}{4\pi \times 10^{-7} \times 1000}$$

$$AT_0 = 2387.32$$

$$I_u = \frac{2387.32}{\sqrt{2} (800)}$$

$$I_u = 2.11 \text{ A}$$

$$I_0 = \sqrt{I_u^2 + I_c^2}$$

$$I_0 = 2.13 \text{ A}$$

$E = 4.44 f B_m A^2 T_P$
 $400 = 4.44 (50) (B_m) (2.25 \times 10^{-3}) \times 800$
 $B_m = 1 \text{ T}$

$$D^2 L = \frac{1}{3.419} \times \frac{262.5}{600}$$

$$D^2 L = 0.127$$

$$b = 4 \sigma$$

$$= 0.7 \frac{\pi D}{P}$$

$$= 0.7 \times \frac{\pi \times D}{P}$$

$$f = \frac{PN}{120}$$

No. of poles
 f - can be 25 - $\frac{120 \times 25}{600} = 5$
 50 - $\frac{120 \times 50}{600} = 10$

Choose No. of poles $\rightarrow 10$

$$L_b = 0.7 \times \frac{\pi \times D}{10}$$

$$L = \frac{0.7 \times \pi \times D}{10}$$

$$L = 0.22 D$$

$$0.22 D^3 = 0.127$$

| |
|-----------------------|
| $D = 0.832 \text{ m}$ |
| $L = 0.183 \text{ m}$ |

Q6.

$$\rightarrow D^2 L = \frac{1}{C_0} \frac{P_a}{N}$$

$$E_a = 0.400 + 3 \times (400)$$

$$E_a = 412 \text{ V}$$

$$I_a = 625 \pm 6.25$$

$$P_a = 250 + (0.05) 250 = 262.5 \text{ kW}$$

$$C_0 = \frac{B_m \mu_r \mu_0 \times \pi^2 \times 10^{-3}}{60}$$

$$= \frac{0.63 \times 23000 \times \pi^2 \times 10^{-3}}{60} = 3.419$$

② No. of conductors

$$E = \frac{P \phi N Z}{60 A}$$

$$B_{av} = \frac{P \phi}{\pi D L}$$

$$E = \frac{B_{av} \pi D L N Z}{60 A}$$

$$P \phi = B_{av} \pi D L$$

$$412 = \frac{0.63 \times \pi \times 0.83 \times 0.18 \times 600 \times Z}{60 \times 10} \quad A = P$$

$$Z = 1393$$



③ No. of slots

$$C_s = \frac{\pi D}{S}$$

$$S = \frac{\pi \times 0.83 Z}{2.6 \times 10^2}$$

$$S = 1.5$$

$$S = 100.5$$

④ No. of conductors / slot

$$\frac{Z}{S} = \frac{1393}{100} \rightarrow 139.3 \approx 14$$

so $Z \rightarrow 1400$

5) Cross sectional area of armature conductor.

$$A_c = \frac{I_z}{8 Z}$$

$$I = 625 A$$

$$I_a \rightarrow 625 + 5 \rightarrow 630$$

$$I_z = \frac{I_a}{A}$$

$$I_z = \frac{630}{10}$$

$$I_z = 63 A$$

$$A_c = \frac{63}{5}$$

$$A_c = 12.6 \text{ mm}^2$$

Q7 a.

Specific magnetic loadings \rightarrow This is ratio of total flux around the air gap to the air gap area.


$$\text{Average flux density in air gap } B_{av} = \frac{P \phi}{\pi D L} \rightarrow (1)$$

P :- Number of poles in d.c. machine.

ϕ :- Airgap flux per pole. μb

D :- diameter of armature. m

L :- gross length of armature. m



Specific electric loadings :- It is total number of ampere conductors on the armature per unit circumference of armature.

$$\text{Specific electric loading } q = \frac{I_a Z_a}{\pi D} \rightarrow (2)$$

I_a :- Current in armature winding A

Z_a :- Number of conductors in each parallel path $\frac{Z}{A}$

D :- diameter of armature m

Number of parallel paths

Output equation:

Power developed by armature.

$$P_a = E \times I_a \times 10^{-3} \text{ KW} \rightarrow (3)$$

$$\text{Induced emf } E = \frac{P \phi N Z_a}{60} \rightarrow (4) \quad Z_a = \frac{Z}{A}$$

Substitute (4) in (3) $N \rightarrow$ Speed in rpm

$$P_a = \frac{P \phi N Z_a}{60} \times I_a \times 10^{-3} \rightarrow (5)$$

From equation (1) & (2)

$$P \phi = B_{av} \pi D L$$

$$I_a Z_a = q \pi D$$

so equation (5) will be

$$P_a = B_{av} \pi D L \times \frac{N}{60} \times q \pi D \times 10^{-3}$$

$$P_a = B_{av} q \frac{\pi^2}{60} D^2 L N \times 10^{-3}$$

$$\frac{P_a}{N} = C_o D^2 L$$

$$C_o = B_{av} q \frac{\pi^2}{60} \times 10^{-3}$$

\downarrow o/p coefficient. $\rightarrow (3)$

$$D^2 L = \left(\frac{1}{C_o} \right) \frac{P_a}{N} \rightarrow (6)$$

Q7. b

Choice of specific loadings

Both magnetic and electrical loadings play an important role in design of dc machine.

These loadings also depend on certain factors which are listed below:-

Choice of average gap density (Specific magnetic loadings)

i) Flux density in teeth:- Flux density at root of teeth should not be $> 2.2T$. If mmf increases field copper loss will increase. Iron losses will also increase at higher flux density.

ii) Frequency:- Frequency of reversals $f = \frac{Pn}{60}$. If this is higher, it will increase iron losses in both armature & field. Frequency reversals increases with increase in flux density. High B_{av} in \uparrow machine.

iii) Size of machine:-

In a well designed machine, we have max. flux density in teeth compared to air gap. So we have to relate B_t & B_{av} .

Flux over one slot pitch = $\frac{P\phi}{S}$

* The max. value of flux density occurs at smallest tooth width.

For smaller machines the variation in tooth width is seen, so as B_t increases to maintain the relation B_{av} must be reduced.

∴ Smaller machines have lower specific magnetic loadings.

Disadvantages due to higher specific magnetic loadings

- * Increased noise, iron loss, copper loss
- * mmf requirement is more, so no load current is more
- * Higher tooth flux density (B_t)
- * Increased temperature due to losses.
- * Saturation of magnetic parts.

Choice of Ampere Conductors per metre (Specific Electrical loadings)


Factors that influence AC/m

Temperature rise limit:-

$$ac = \frac{I_a Z_a}{\pi D} = \frac{I_a Z_a / s}{\pi D / s} = \frac{I_a Z_s}{Y_s}$$

$$I^2 R \text{ loss} = I_a^2 \left(\frac{sL}{az} \right) \text{ in slot portion of each conductor}$$

$$= I_a^2 \frac{sL}{z} \text{ in each conductor}$$

$$= z \frac{I_a^2 sL}{az} \text{ each slot}$$


Heat dissipating surface = $Y_s L$

Loss dissipated $z = \frac{\text{Loss}}{\text{surface}} = \frac{z \frac{I_a^2 sL}{az}}{Y_s L}$

$$ac = \frac{I_a Z_a}{Y_s}$$

1) Temperature rise \rightarrow Insulating material plays an important role. Semi-closed machines are good.

2) Speed of machine \rightarrow with good ventilation more 'ac' can be used.

3) Voltage \rightarrow larger space is required for insulation. So less space for conductors.

4) Armature reaction \rightarrow as 'ac' increases conductor's mmf increase, which in turn increases field mmf. Hence, cost is increased.

5) Commutation: $ac = \frac{I_a Z}{\pi D}$ small D & higher z for higher ac. (reason - inductance)

⑥ Size of machine :

Area of each slot = height of slot \times width of slot
 $d_s \times w_s$

$$\begin{aligned} \text{Total area of all slots} &= S d_s w_s \\ &= \frac{\pi D}{y_s} d_s w_s S_f \end{aligned}$$

$$\begin{aligned} \text{Total area of conductors} &= Z a_s \\ &= Z (I_z / \delta) a_s \\ &= a_c \frac{\pi D}{\delta} a_s \end{aligned}$$

$$\frac{I_z}{a_s} = \delta \quad a_c = \frac{I_z Z}{\pi D}$$

$$\frac{\pi D a_c}{\delta} = \frac{\pi D}{y_s} d_s w_s S_f$$

$$a_c = \delta \frac{\pi D}{y_s} d_s S_f w_s$$

Disadvantages due to higher specific electrical loadings

- * Increased field excitation, \uparrow field cu loss.
- * \uparrow armature copper loss.
- * \uparrow reactance voltage \downarrow commutation.
- * \uparrow temperature.
- * reduced overload capacity

Advantages of higher specific loadings

- * \downarrow size of machine, weight of m/c
- * lower overall cost, cost of materials
- * volume of m/c