				. A
and the sale				A.
The same of the sa	1 1		1 1	48
GO NE STATE		1 1 -		
CALLET TO THE PARTY OF THE PART	1 1	- No. 18 18 - 249		THE STREET AS AND DOMESTICAL DEPT.
				9.6

15EE64

# Sixth Semester B.E. Degree Examination, Jan./Feb. 2021 **Electrical Machine Design**

Time: 3 hrs.

Max. Marks: 80

Note: Answer any FIVE full questions, choosing ONE full question from each module.

# Module-1

Discuss the factors which imposes limitations on design 1

(08 Marks)

What are the desirable properties of insulating materials? Explain the classification of b. insulating materials based on thermal consideration. (08 Marks)

### OR

What are the factors to be considered for design of electrical machines? a.

(05 Marks)

Classify the soft magnetic materials with examples. b.

(05 Marks)

What are the properties of high conductivity materials? c.

(06 Marks)

# Module-2

- Briefly discuss about the factors which influence the selection of number of poles of a DC 3 (06 Marks) machine.
  - b. Derive output equation of a DC machine.

(05 Marks)

c. A 5KW, 250V, 4 pole, 1500rpm DC shunt generator is designed to have a square pole face. Average flux density in air gap = 0.42 Wb/m<sup>2</sup>, specific electric loading = 15000ac/m, full load efficiency = 87% ratio of pole arc to pole pitch = 0.66. Determine the main dimensions (05 Marks) of the machine.

- What are the factors to be considered while selecting large number of armature slots for a DC machine?
  - A 440V, 6 pole DC generator has following data mmf per pole = 7000A, depth of winding = 50mm, length of inner turn = 1.1m, length of outer turn = 1.4m, space factor = 0.62, resistivity =  $2.1 \times 10^{-8} \Omega$  - m, loss radiated from outer surface excluding ends =  $1400 \text{W/m}^2$ and assume a voltage drop of 20% of terminal voltage across the field regulator. Determine number of turns of each field coil and height of field coil. (10 Marks)

## Module-3

- Derive output equation of a three phase core type transformer. Obtain relation between emf 5 per turn and KVA per phase of transformer. (08 Marks)
  - Determine overall dimensions for a 200KVa, 50Hz, single phase core type transformer from the following data. EMF/turn = 14 volts, maximum flux density = 1.1 Wb/m<sup>2</sup>, window space factor = 0.32, current density = 3A/mm<sup>2</sup>, stacking factor = 0.9. A cruciform core is used with distance between core centers = 0.435m. The net iron area is 0.56d<sup>2</sup> where d is the diameter of circumscribing circle. Width of largest stamping = 0.85d. Assume cruciform section for (08 Marks) the Yoke

- 6 a. Determine no load current of a single phase 400V, 50Hz transformer from the following data. Length of mean flux path = 2.2m, net iron area = 9 × 10<sup>-3</sup>m<sup>2</sup>, primary turns = 200. Joints equivalent to 0.2mm air gap. For a working flux density of 1Wb/m<sup>2</sup>, iron loss is 1.3W/kg and mmf/m = 210A. Iron weighs 7.8 × 10<sup>3</sup>kg/m<sup>3</sup>. (08 Marks)
  - b. The tank of a natural oil cooled transformer has the dimensions length, width and height as 1m, 0.5m and 1.25m respectively. The full load loss is 4800W. Design a suitable scheme for cooling tubes if the average temperature rise is to be limited to 35°C. The diameter of the tube is 50mm and are spaced 75mm from each other. The average height of the tube is 1.05m. Assume that convection is improved by 35% due to provision of tubes. (08 Marks)

# Module-4

- 7 a. Discuss the various factors that influence the choice of length of the air gap of an induction motor.

  (07 Marks)
  - b. A 40hp, 50Hz, 6pole, 440V, delta connected three phase induction motor has teeth following data. specific magnetic loading = 0.48 Wb/m², specific electric loading = 26000 ac/m, ratio of core length to pole pitch = 1, efficiency = 88%, power factor = 0.86. Winding factor = 0.955. Determine the main dimensions, stator turns per phase, number of stator slots and conductors per slot. (09 Marks)

### OR

- 8 a. A 11 KW, 6pole, 50Hz 220 voltage star connected three phase induction motor has 54 stator slots with 9 conductors per slot. Calculate values of bar and end ring currents. The number of rotor slots = 64. The machine has an efficiency of 0.86 and a power factor of 0.85. The rotor mmf equals to 85% of stator mmf. Also determine the bar and end ring sections if the current density is 5A/mm<sup>2</sup>. (08 Marks)
  - b. A 15 KW, 400V, 50Hz, 6 pole, three phase induction motor has a diameter of 0.3m and length of core = 0.12m. The number of stator slots is 72 with 20 conductors per slot. The stator is delta connected. Stator winding factor = 0.96. The gap contraction factor is 1.2. Assume the mmf required for the iron parts to be 35% of the air gap mmf. Calculate the value of magnetising current per phase if the length of the air gap is 0.55mm. (08 Marks)

#### Module-5

- 9 a. Drive the output equation of a synchronous machine. (08 Marks)
  - b. During the design of stator of 7500KVA, 6.6KV, 50Hz, 3000rpm, three phase alternator the following data has been obtained. Stator diameter = 0.75m, core length = 0.9m, number of stator slots/pole/phase = 7. Number of conductors per slot = 4. Winding factor = 0.955 cross sectional area of stator conductor = 190mm<sup>2</sup>. Determine flux per pole, specific magnetic loading, specific electric loading and current density for the stator winding. (08 Marks)

### OR

- 10 a. Define short circuit ratio for a synchronous generator. Explain effects of short circuit ratio on synchronous machine performance. (08 Marks)
  - b. A 500KVA, 3.3 KV, 50Hz, 600rpm, three phase salient pole alternator has 180 turns per phase, field form factor = 0.66. Short circuit ratio = 1.2, winding factor = 0.955, gap contraction factor = 1.15. The mmf required for air gap is 80% of no load field mmf. Determine the length of air gap of the average flux density is 0.54 Wb/m<sup>2</sup> (08 Marks)



