

Transformers & Generators-18EE33

Your email address (kodandapani.d@cmrit.ac.in) will be recorded when you submit this form. Not you? [Switch account](#)

* Required

Name of the Student *

Your answer

USN Number *

Your answer

Email id: *

Your answer

The open-circuit test in a transformer is used to measure *

1 point

- 1. Copper loss
- 2. Winding loss
- 3. Total loss
- 4. Core loss



Lamination of the transformer core is made of *

1 point

- 1. Cast Iron
- 2. Silicon Steel
- 3. Aluminum
- 4. Cast Steel

Which of the following losses varies with the load in the transformer? *

1 point

- 1. Core loss
- 2. Copper loss
- 3. Both core & copper loss
- 4. None of the above

How many primary volts must be applied to a transformer with a turns ratio of 0.1 to obtain a secondary voltage of 9 V? *

1 point

- 9 V
- 90 V
- 900 V
- 0.9 V



Transformer core are laminated in order to *

1 point

- 1. reduce hysteresis loss
- 2. reduce hysteresis & eddy current loss
- 3. minimize eddy current loss
- 4. Copper loss

A transformer has negative voltage regulation when its load power factor is *

1 point

- 1. Lagging
- 2. Leading
- 3. Unity
- 4. Any of the above

The main purpose of performing short circuit test in a transformer is to measure its *

1 point

- 1. Copper loss
- 2. Core loss
- 3. Insulation Resistance
- 4. Total loss



The short circuit test in a transformer is performed on *

1 point

- 1. Low voltage side
- 2. High voltage side
- 3. Either 1 & 2
- 4. Both 1 & 2

The transformer ratings are usually expressed in terms of *

2 points

- 1. KW
- 2. KVAR
- 3. KVA
- 4. Volts

Which winding in a transformer has more number of turns? *

2 points

- 1. Secondary winding
- 2. primary winding
- 3. High voltage winding
- 4. Low voltage winding
- Option 5



Iron loss in a transformer can be determined by *

2 points

- 1. Open circuit test
- 2. Short Circuit test
- 3. Both 1 & 2
- 4. None of the above

The path of magnetic flux in a transformer should have *

2 points

- 1. Low resistance
- 2. Low reluctance
- 3. High Resistance
- 4. High Reluctance

What would happen if a transformer is connected to a DC supply? *

2 points

- 1. No effect
- 2. Operate with high efficiency
- 3. Damage the transformer
- 4. Operate with low frequency



The friction loss in a transformer is *

2 points

- 1. 20%
- 2. 0%
- 3. 50%
- 4. more than 50%

During the open circuit test of a transformer *

2 points

- 1. Primary is supplied rated voltage
- 2. Primary is supplied current at reduce the voltage
- 3. Primary is supplied rated KVA
- 4. Primary is supplied full load current

A good voltage regulation of a transformer means *

2 points

- Output voltage fluctuation from no load to full load is least
- Output voltage fluctuation with power factor is least
- Difference between input voltage and output voltage is least
- Difference between input voltage and output voltage is maximum



Open delta transformers can be obtained from *

1 point

- delta-delta
- star-delta
- delta-star
- any of the mentioned

If one of the transformers is removed from the bank of only delta-delta, then it behaves with 58% power delivery. *

1 point

- True
- False

Scott connections are used in *

1 point

- three-phase to single phase transformation
- three-phase to two-phase transformation
- single phase to three-phase transformation
- all phase transformations



Open delta connection has VA rating of *

1 point

- $\sqrt{3}$ times delta/delta VA rating
- $1/\sqrt{3}$ times delta/delta VA rating
- 3 times delta/delta VA rating
- $1/3$ times delta/delta VA rating

In a 5 kV / 400V, 75 kVA single phase transformer, the current flowing in the primary winding of transformer is 10A. what will be the current flowing in the secondary winding? *


2 points

- 100A
- 120A
- 125A
- 130A

A 600 kVA transformer has iron losses of 400 kW and copper losses of 500 kW. Its kVA rating for maximum efficiency is given by *

2 points

- 537 kVA
- 548 kVA
- 555 kVA
- 585 kVA



In a 20 kVA, 2200 / 220 volts transformer iron and copper losses are 300 and 400 watts respectively. Its efficiency at half load and unity power factor is *

2 points

- 95.11%
- 96.15%
- 97.77%
- 98%

When a resistance is to be transferred from primary to secondary side of transformer with the turns ratio as k , it must be *

2 points

- Multiplied by k^2
- Multiplied by k
- Divided by k
- Divided by k^2

The most commonly used connections for power systems as a step - up and step - down transformers are *

2 points

- Star - delta, star - star
- Delta - star, star - delta
- Star - star, delta - delta
- Star - delta, delta - star



For a single phase no load transformer, which among the following losses will be minimum? * 2 points

- hysteresis losses
- eddy current losses
- copper losses
- mechanical losses

In T-T connection, the percentage tapping of main transformer and teaser transformer are * 2 points

- 50%, 86.6%
- 50%, 50%
- 86.6%, 86.6%
- 86.6%, 50%

In star-star connection of three phase transformer, if V_L is the line voltage and I_L is the line current then phase voltage and phase current is given by * 2 points

- $V_L / \sqrt{3}, I_L$
- V_L, I_L
- $\sqrt{3}V_L, I_L / \sqrt{3}$
- $V_L, I_L / \sqrt{3}$



For maximum efficiency in a transformer *

1 point

- Core losses = 2 * copper losses
- Core losses = copper losses / 2
- Core losses = copper losses
- Core losses = copper losses \wedge 2

A 10 kVA, 2000 / 100v transformer has $R_1=1.5$ ohm, $R_2=0.005$ ohm, $X_1=2.5$ ohm and $X_2=0.08$ ohm. The equivalent resistance referred to primary is *

2 points

- 3 ohm
- 3.25 ohm
- 3.5 ohm
- 3.8 ohm

In a Transformer , The primary flux is always _____ the secondary (flux). *

1 point

- Greater then
- Smaller then
- Equal
- Equal in both step up and Step down Transformer



E.M.F Equation of the Transformer is _____.*

2 points

- $E_1 = 4.44 f N_1 \phi_m$, $E_2 = 4.44 f N_2 \phi_m$
- $E_1 = 4.44 f N_1 B_m A$, $E_2 = 4.44 f N_2 B_m A$
- $E_1 = 4.44 N_1 \phi_m/T$, $E_2 = 4.44 N_2 \phi_m/T$
- All of the above

Send me a copy of my responses.

Submit

Never submit passwords through Google Forms.

This form was created inside of CMR Institute of Technology. [Report Abuse](#)

Google Forms



Transformers & Generators-18EE33

Your email address (kodandapani.d@cmrit.ac.in) will be recorded when you submit this form. Not you? [Switch account](#)

* Required

Name of the Student *

Your answer

USN Number *

Your answer

Email id: *

Your answer

The open-circuit test in a transformer is used to measure *

1 point

- 1. Copper loss
- 2. Winding loss
- 3. Total loss
- 4. Core loss



Lamination of the transformer core is made of *

1 point

- 1. Cast Iron
- 2. Silicon Steel
- 3. Aluminum
- 4. Cast Steel

Which of the following losses varies with the load in the transformer? *

1 point

- 1. Core loss
- 2. Copper loss
- 3. Both core & copper loss
- 4. None of the above

How many primary volts must be applied to a transformer with a turns ratio of 0.1 to obtain a secondary voltage of 9 V? *

1 point

- 9 V
- 90 V
- 900 V
- 0.9 V



Transformer core are laminated in order to *

1 point

- 1. reduce hysteresis loss
- 2. reduce hysteresis & eddy current loss
- 3. minimize eddy current loss
- 4. Copper loss

A transformer has negative voltage regulation when its load power factor is *

1 point

- 1. Lagging
- 2. Leading
- 3. Unity
- 4. Any of the above

The main purpose of performing short circuit test in a transformer is to measure its *

1 point

- 1. Copper loss
- 2. Core loss
- 3. Insulation Resistance
- 4. Total loss



The short circuit test in a transformer is performed on *

1 point

- 1. Low voltage side
- 2. High voltage side
- 3. Either 1 & 2
- 4. Both 1 & 2

The transformer ratings are usually expressed in terms of *

2 points

- 1. KW
- 2. KVAR
- 3. KVA
- 4. Volts

Which winding in a transformer has more number of turns? *

2 points

- 1. Secondary winding
- 2. primary winding
- 3. High voltage winding
- 4. Low voltage winding
- Option 5



Iron loss in a transformer can be determined by *

2 points

- 1. Open circuit test
- 2. Short Circuit test
- 3. Both 1 & 2
- 4. None of the above

The path of magnetic flux in a transformer should have *

2 points

- 1. Low resistance
- 2. Low reluctance
- 3. High Resistance
- 4. High Reluctance

What would happen if a transformer is connected to a DC supply? *

2 points

- 1. No effect
- 2. Operate with high efficiency
- 3. Damage the transformer
- 4. Operate with low frequency



The friction loss in a transformer is *

2 points

- 1. 20%
- 2. 0%
- 3. 50%
- 4. more than 50%

During the open circuit test of a transformer *

2 points

- 1. Primary is supplied rated voltage
- 2. Primary is supplied current at reduce the voltage
- 3. Primary is supplied rated KVA
- 4. Primary is supplied full load current

A good voltage regulation of a transformer means *

2 points

- Output voltage fluctuation from no load to full load is least
- Output voltage fluctuation with power factor is least
- Difference between input voltage and output voltage is least
- Difference between input voltage and output voltage is maximum



Open delta transformers can be obtained from *

1 point

- delta-delta
- star-delta
- delta-star
- any of the mentioned

If one of the transformers is removed from the bank of only delta-delta, then it behaves with 58% power delivery. *

1 point

- True
- False

Scott connections are used in *

1 point

- three-phase to single phase transformation
- three-phase to two-phase transformation
- single phase to three-phase transformation
- all phase transformations



Open delta connection has VA rating of *

1 point

- $\sqrt{3}$ times delta/delta VA rating
- $1/\sqrt{3}$ times delta/delta VA rating
- 3 times delta/delta VA rating
- $1/3$ times delta/delta VA rating

In a 5 kV / 400V, 75 kVA single phase transformer, the current flowing in the primary winding of transformer is 10A. what will be the current flowing in the secondary winding? *

2 points

- 100A
- 120A
- 125A
- 130A

A 600 kVA transformer has iron losses of 400 kW and copper losses of 500 kW. Its kVA rating for maximum efficiency is given by *

2 points

- 537 kVA
- 548 kVA
- 555 kVA
- 585 kVA



In a 20 kVA, 2200 / 220 volts transformer iron and copper losses are 300 and 400 watts respectively. Its efficiency at half load and unity power factor is *

2 points

- 95.11%
- 96.15%
- 97.77%
- 98%

When a resistance is to be transferred from primary to secondary side of transformer with the turns ratio as k , it must be *

2 points

- Multiplied by k^2
- Multiplied by k
- Divided by k
- Divided by k^2

The most commonly used connections for power systems as a step - up and step - down transformers are *

2 points

- Star - delta, star - star
- Delta - star, star - delta
- Star - star, delta - delta
- Star - delta, delta - star



For a single phase no load transformer, which among the following losses will be minimum? * 2 points

- hysteresis losses
- eddy current losses
- copper losses
- mechanical losses

In T-T connection, the percentage tapping of main transformer and teaser transformer are * 2 points

- 50%, 86.6%
- 50%, 50%
- 86.6%, 86.6%
- 86.6%, 50%

In star-star connection of three phase transformer, if V_L is the line voltage and I_L is the line current then phase voltage and phase current is given by * 2 points

- $V_L / \sqrt{3}, I_L$
- V_L, I_L
- $\sqrt{3}V_L, I_L / \sqrt{3}$
- $V_L, I_L / \sqrt{3}$



For maximum efficiency in a transformer *

1 point

- Core losses = 2 * copper losses
- Core losses = copper losses / 2
- Core losses = copper losses
- Core losses = copper losses \wedge 2

A 10 kVA, 2000 / 100v transformer has $R_1=1.5$ ohm, $R_2=0.005$ ohm, $X_1=2.5$ ohm and $X_2=0.08$ ohm. The equivalent resistance referred to primary is *

2 points

- 3 ohm
- 3.25 ohm
- 3.5 ohm
- 3.8 ohm

In a Transformer , The primary flux is always _____ the secondary (flux). *

1 point

- Greater then
- Smaller then
- Equal
- Equal in both step up and Step down Transformer



E.M.F Equation of the Transformer is _____.*

2 points

- $E_1 = 4.44 f N_1 \phi_m$, $E_2 = 4.44 f N_2 \phi_m$
- $E_1 = 4.44 f N_1 B_m A$, $E_2 = 4.44 f N_2 B_m A$
- $E_1 = 4.44 N_1 \phi_m/T$, $E_2 = 4.44 N_2 \phi_m/T$
- All of the above

Send me a copy of my responses.

Submit

Never submit passwords through Google Forms.

This form was created inside of CMR Institute of Technology. [Report Abuse](#)

Google Forms

