

Internal Assessment Test – 2

Sub: Special Electrical Machines (Professional Elective)				Code: 17EE554
Date: 14/10/2019	Duration: 90 mins	Max Marks: 50	Sem: 5	Sections: A&B
Answer ANY FIVE full questions. Explain your notations explicitly and clearly. Sketch figures wherever necessary. Good luck!				

Marks	OBE	
	CO	RBT
Q1a. With a neat circuit diagram and current & torque waveforms, explain the following types of BLDC motors (i) one-phase and one pulse; and (ii) one-phase and two pulse. [6]	CO1	L2
Q1b. Compare BLDC motor and conventional DC motor. [4]	CO1	L1
Q2. A permanent magnet DC (PMDC) motor has an armature resistance of $1.03\ \Omega$. It draws a current of $1.25\ A$ at no load with $50\ V$ supply and running at $2100\ rpm$. Find (i) speed-voltage constant; (ii) rotational losses; and (iii) output power when it runs at $1700\ rpm$ at $48\ V$ supply. [10]	CO1	L3
Q3. Derive the EMF equation of permanent magnet synchronous motor (PMSM). [10]	CO2	L3
Q4. A 3-phase, 4 pole, $50\ Hz$, $400\ V$, star connected synchronous reluctance motor (SyRM) has direct axis and quadrature axis synchronous reactances of $8\ \Omega$ and $2\ \Omega$ respectively. For a load torque of $80\ N\cdot m$, find (i) load angle; (ii) line current; and (iii) power factor. neglect armature resistance and mechanical losses. [10]	CO1	L3
Q5. Explain with a neat circuit diagram the DSP-based control of PMSM. [10]	CO3	L2
Q6a. List any eight applications of SyRM. [4]	CO1	L1
Q6b. A 3-phase, 4 pole, star connected PMSM has 72 slots with 20 conductors/slot. The flux/pole is $0.05\ Wb$ and the speed is $1500\ rpm$. Assuming full pitched coil, find the phase and line voltage. Assume $K_s = 1$ and $K_d = 0.986$. [6]	CO1	L3

Internal Assessment Test – 2

Sub: Special Electrical Machines (Professional Elective)				Code: 17EE554
Date: 14/10/2019	Duration: 90 mins	Max Marks: 50	Sem: 5	Sections: A&B
Answer ANY FIVE full questions. Explain your notations explicitly and clearly. Sketch figures wherever necessary. Good luck!				

Marks	OBE	
	CO	RBT
Q1a. With a neat circuit diagram and current & torque waveforms, explain the following types of BLDC motors (i) one-phase and one pulse; and (ii) one-phase and two pulse. [6]	CO1	L2
Q1b. Compare BLDC motor and conventional DC motor. [4]	CO1	L1
Q2. A permanent magnet DC (PMDC) motor has an armature resistance of $1.03\ \Omega$. It draws a current of $1.25\ A$ at no load with $50\ V$ supply and running at $2100\ rpm$. Find (i) speed-voltage constant; (ii) rotational losses; and (iii) output power when it runs at $1700\ rpm$ at $48\ V$ supply. [10]	CO1	L3
Q3. Derive the EMF equation of permanent magnet synchronous motor (PMSM). [10]	CO2	L3
Q4. A 3-phase, 4 pole, $50\ Hz$, $400\ V$, star connected synchronous reluctance motor (SyRM) has direct axis and quadrature axis synchronous reactances of $8\ \Omega$ and $2\ \Omega$ respectively. For a load torque of $80\ N\cdot m$, find (i) load angle; (ii) line current; and (iii) power factor. neglect armature resistance and mechanical losses. [10]	CO1	L3
Q5. Explain with a neat circuit diagram the DSP-based control of PMSM. [10]	CO3	L2
Q6a. List any eight applications of SyRM. [4]	CO1	L1
Q6b. A 3-phase, 4 pole, star connected PMSM has 72 slots with 20 conductors/slot. The flux/pole is $0.05\ Wb$ and the speed is $1500\ rpm$. Assuming full pitched coil, find the phase and line voltage. Assume $K_s = 1$ and $K_d = 0.986$. [6]	CO1	L3

[Handwritten signatures over the Q6b row]

ASSIGNMENT- 2

ELECTRICAL AND ELECTRONICS ENGG [MR. KASHIF AHMED]

NAME:- ANINDITA BISWAS

CLASS & SECTION:- '5'- 'A' EEE

USN :- 1CR17EE006


DUE DATE FOR SUBMISSION:- 17th OCTOBER 2019

DATE OF SUBMISSION:- 17th OCTOBER 2019


- 1) With a neat circuit diagram and current & torque waveforms, explain the following types of BLDC motors
 (i) one-phase and one pulse; and (ii) one phase and two pulse.

Soln.one phase and one pulse BLDC motor:-

- It has only one armature winding
- It uses only one semiconductor switch.
- When the rotor position sensor is influenced by N pole, the switch is turned ON and turned OFF when the sensor is influenced by S pole.
- Thus, torque is developed only for half cycle.
- Here the utilization of transistors and winding is 50%.
- The current and torque waveforms are shown below.




one phase one pulse motor

one phase and two pulse BLDC motor:-

- This motor has one armature winding and two static switches which are used to supply the armature.
- This requires a three phase AC supply and better

winding utilisation.

- This scheme requires a position sensor and two switching devices, and S_2 .
- S_1 is switched ON when the sensor is under the influence of N pole and is switched OFF when it is under the influence of S pole.
- S_2 is turned ON only when the sensor is influenced by S pole and switched OFF when it is influenced by N pole.



1b) Compare BLDC motor and conventional Dcmotor.

sofn

BLDC motor	Conventional Dcmotor
1- Permanent magnet field system is on the rotor	1- Electromagnetic field system on stator.
2 - Armature is on stator	2- Armature is on rotor.
3- Commutation is done by power semiconductor device.	3- Commutation is done by brushes and commutators mechanically.
4- Star or delta connected armature winding.	4- Ring type armature winding
5 - Rotor position should be sensed and feedback for switching of static switches.	5- Position is automatically sensed and no external sensor for feedback is needed.
6- Direction of rotation is changed by changing the switching sequence.	6- Direction is changing by interchanging the terminals of armature or field.

- 2) A permanent magnet DC (PMDc) motor has an armature resistance of 1.03Ω . It draws a current of $1.25A$ at no load with $50V$ supply and running at 2100 rpm . Find
 (i) Speed - voltage constant; (ii) rotational losses; and
 (iii) Output power when it runs at 1700 rpm at $48V$ supply

Solt.

Given : $R_a = 1.03\Omega$; $I = 1.25A$; $V = 50V$; $N = 2100\text{ rpm}$.

$$E_b = V - I_a R_a$$

$$E_b = 50 - (1.03 \times 1.25)$$

$$E_b = 48.71V$$

$$\omega = \frac{2\pi N}{60} = \frac{2\pi \times 2100}{60} = 219.91 \text{ rad/s}$$

$$E_b = k_T \omega$$

$$(i) k_T = \frac{E_b}{\omega} = \frac{48.71}{219.91} = 0.2215 \text{ V/rad/s.}$$

$$(ii) \text{Rotational losses} = E_b I_a = 48.71 \times 1.25 \\ = 60.89W.$$

(iii) Output power when $N = 1700\text{ rpm}$, $V = 48V$.

$$k_T = 0.2215 \text{ V/rad/s}, \omega = \frac{2\pi N}{60} = \frac{2\pi \times 1700}{60} = 178.02 \text{ rad/s.}$$

$$E_b = k_T \omega = 0.2215 \times 178.02$$

$$E_b = 39.43V.$$

$$I_a = \frac{V - E_b}{R_a} = \frac{48 - 39.43}{1.03} = 8.32A$$

$$\text{Power developed} = E_b I_a = 39.43 \times 8.32 = 328.057W$$

$$\therefore P_{eff} = 328.057 - 60.89 \\ = 267.16W$$

3)

Derive the EMF equation of permanent magnet synchronous motor (PMSM).

Solt.

EMF Equation of PMSM :-

Let B = flux density, Tesla

B_{max} = maximum flux density, Tesla.

P = number of pole pairs.

ω_m = mechanical rotor velocity, rad/s.

θ_m = mechanical rotor position

ω_e = electrical rotor velocity

θ_e = electrical rotor position

e_{ph} = instantaneous emf per phase

$E_{ph\max}$ = Maximum emf per phase

E_{ph} = RMS value of induced emf per phase.

ϕ = flux, wb (instantaneous).

ϕ = flux/pole, wb.

l = length of armature, m

r = radius of armature, m.

k_{si}^o = skew factor for fundamental component

k_{pi}^o = Chording factor for fundamental component

k_{di}^o = distribution factor for fundamental component.

k_{wi}^o = Winding factor.



A = Ampere Conductor density

A_{max} = Maximum ampere conductor density.

T_{ph} = turns per phase

f = frequency, Hz.

α = angle between the axis of ampere conductor density and flux density distribution.



Flux density in the air gap of PMSM is represented as
Sine wave $B = B_{max} \sin \theta_m$

Incremental of flux in slot, $d\phi = B_{max} l r \sin \theta_m d\alpha$

Flux enclosed by the coil in the position shown is:

$$\phi = \int_{\theta_m t}^{\theta_m t + \pi/p} d\phi = \int_{\theta_m t}^{\theta_m t + \pi/p} B_{max} l r \sin \theta_m d\alpha.$$

$$\phi = B_{max} l_2 \left[-\frac{\cos \rho_0}{P} \right]^{W_{rot} + \frac{1}{4} P}$$

(ii) $\phi = \frac{2B_{max}}{P} l_2 \cos \rho_{rot}$

The emf induced in single turn coil is given by

$$e_{turn} = -\frac{d\phi}{dt} = -\frac{d}{dt} \left[\frac{2B_{max} l_2}{P} \cdot \cos \rho_{rot} \right]$$

$$= 2B_{max} l_2 \omega_{rot} \sin \rho_{rot}$$

The emf induced per phase (instantaneous) is

$$\begin{aligned} e_{ph} &= T_{ph} \times e_{turn} \\ &= 2B_{max} l_2 \omega_{rot} T_{ph} \sin \rho_{rot} \end{aligned}$$

$$e_{ph} = 2B_{max} l_2 \omega_{rot} T_{ph} \sin \rho_{rot}$$

$$e_{ph} = E_{phmax} \sin \rho_{rot}$$

$$e_{ph} = E_M \sin \omega t$$

$$\omega t = \omega M \cdot \tau$$

$$\omega M = \frac{\omega t}{P}$$

$$E_{phmax} = 2B_{max} l_2 T_{ph} \omega_{rot}$$

$$\text{Flux per pole}, \phi = B_{av} \times \frac{2\pi r}{2p} \cdot l$$

$$B_{av} = \frac{2}{\pi} B_{max}$$

$$\phi = \frac{2}{\pi} B_{max} \frac{\pi r l}{P}$$

$$B_{max} \cdot r l = \frac{\pi \phi}{2}$$

$$E_{phmax} = 2 B_{max} r l T_{ph} \omega_{rot}$$

$$E_{phmax} = 2 \cdot \frac{\pi \phi}{2} \cdot T_{ph} \cdot \frac{\omega t}{P} = \phi T_{ph} \omega t = 2\pi f \phi T_{ph}$$

$$T_{ph} = \frac{E_{phmax}}{\sqrt{2}}$$

$$T_{ph} = \sqrt{2\pi f} \phi T_{ph}$$

$$T_{ph} = 4.44 f \phi T_{ph} \rightarrow \textcircled{1}$$

EMF eqn of PMSM if all slots are not skewed ($k_{sl} = 1$)

if winding are full pitched ($k_{ph} = 1$)

if winding are not distributed ($k_{di} = 1$)

$$\mathcal{E}_{ph} = 4.44 f \phi T_{ph} k_{pi} k_{di} k_{ei}$$

$$\mathcal{E}_{ph} = 4.44 f \phi T_{ph} k_{ei}$$

$$k_{ei} = k_{pi} k_{di}$$

$$k_{pi} = \frac{\sin \alpha/2}{\alpha/2}$$


$$k_{di} = \frac{\cos \delta}{2}$$

$$k_{ei} = \frac{\sin \beta/2}{\beta/2}$$

5) Explain with a neat circuit diagram the DSP based control of PMSM.

DSP based control of PMSM :-

- It has a simple rectifier for converting input AC into DC and an inverter to supply the PMSM.
- The controller has the inputs, reference speed, ω_{ref} , rotor position signal & and stator current signals i_x^* and i_y^* . The controller outputs the signals for turning on the IGBTs. The main function of the controller is to generate appropriate triggering signals for the thyristors.



- Functions of the Controller can be achieved by using a DSP with simple software.
- The implementation of Controller using DSP is shown.
- The scheme is developed on the base of vector control.

6.0) List any eight applications of synRM.

solt.

Applications:

- 1) SynRM are used in pumps or conveyors for proportioning devices.
- 2) synthetic fibre manufacturing industries.
- 3) In wrapping and folding machines.
- 4) For positioning of Control rods in nuclear reactors.
- 5) In synchronised textile drives.
- 6) For processing of continuous sheet or film material.
- 7) In constant speed applications such as recording instruments, control apparatus.
- 8) regulators, time devices, phonograph turntable & so on.

6.6) A 3-phase, 4 pole, star connected PMSM has 72 slots with 20 conductors /slot. The flux /pole is 0.05wb and the speed is 1500 rpm. Assuming full pitched coil /phase the phase and line voltage. Assume $k_s = 1$ and $k_d = 0.986$.

Solt. Given: 3- ϕ , P=4, $\phi = 0.05\text{wb}$, N=1500 rpm

$$Z = 72 \times 20 = 1440 \text{ conductors}$$

$$T_{ph} = \frac{Zph}{2} = \frac{1440}{2} = 240$$

$$E_{ph} = 4.44 \times \phi \times f \times T_{ph} \times k_d \times k_s \times k_c$$

$$N = \frac{120f}{P} \Rightarrow f = \frac{PN}{120} = \frac{4 \times 1500}{120} = 50 \text{ Hz}$$

$$E_{ph} = 4.44 \times 0.05 \times 50 \times 240 \times 1 \times 1 \times 0.986$$

$$E_{ph} = 2626.704 \text{ V.}$$

$$E_L = \sqrt{3} \times E_{ph} = \sqrt{3} \times 2626.704$$

$$E_L = 4549.58 \text{ V.}$$

- 4) A 3-phase, 4 pole, 50 Hz, 400 V star connected synchronous reluctance motor (synRM) has direct axis and quadrature axis synchronous reactance of 8- Ω & 2- Ω respectively. For a load torque of 80 N-m. Find its load angle i i) line current and ii i) power factor neglect armature resistance & mechanical losses.

Soln.

Given: 3 ϕ , P=4, V₁=400V, X_{ds}=8- Ω , X_{qs}=2- Ω , T=80 N-m

Star Connected, $V_{ph} = \frac{V_1}{\sqrt{3}} = \frac{400V}{\sqrt{3}} = 230.94 \text{ V.}$

i) $T = \frac{3}{ws} V_{ph}^2 \frac{X_{ds} - X_{qs}}{2 X_{ds} X_{qs}} \sin 2\delta$.

$$ws = \frac{2\pi f}{P/2} = \frac{2\pi \times 50}{4/2} = 157.079 \text{ rad.}$$

$$\sin 2\delta = \frac{80 \times 157.079 \times 2 \times 8 \times 2}{3 \times (230.94)^2 \times (8-2)} = 0.4188$$

$$\alpha\delta = 24.76 \Rightarrow \boxed{\delta = 12.38^\circ}$$

ii) $I_{ph} = I_L = \sqrt{I_d^2 + I_q^2}$

$$I_d = \frac{V \cos \delta}{X_{ds}} = \frac{230.94 \times \cos(12.38)}{8} = 28.19 \text{ A.}$$

$$I_q = \frac{V \sin \delta}{X_{qs}} = \frac{230.94 \times \sin(12.38)}{2} = 24.75 \text{ A.}$$

$$I = \sqrt{(28.19)^2 + (24.75)^2} = 37.51 \text{ A}$$

iii) $P = \sqrt{3} V_1 I_L \cos \phi$

$$P = \frac{P}{ws} \Rightarrow P = T ws = 80 \times 157.079 = 12566.32 \text{ W.}$$

$$\cos \phi = \frac{12566.32}{\sqrt{3} \times 400 \times 37.51} = 0.4835.$$