

Basic Electrical Engineering (18ELE23): IAT 3

The respondent's email (**null**) was recorded on submission of this form.

* Required

1. Email *

2. NAME *

Untitled Section

3. USN *

4. SECTION *

Mark only one oval.

I

J

K

L

M

N

O

QUESTIONS

5. A transformer core is laminated to reduce *

Mark only one oval.

- hysteresis loss
- eddy current loss
- leakage reactance
- all of the above

6. The transformer efficiency is maximum when *

Mark only one oval.

- $P_i > P_{cu}$
- $P_i < P_{cu}$
- $P_i = P_{cu}$
- none of these

7. Transformation ratio of a transformer is equal to *

Mark only one oval.

- E_1/E_2
- N_1/N_2
- N_2/N_1
- I_2/I_1

8. In a step up transformer, the following remains constant *

Mark only one oval.

- voltage
- current
- power
- none of these

9. For 400 V/ 100 V transformer, the secondary turns are 16, then the primary turns are *

Mark only one oval.

- 4
- 64
- 16
- 8

10. Which loss is variable in a transformer ? *

Mark only one oval.

- eddy current
- copper
- hysteresis
- friction

11. The copper loss of a transformer at half full load is measured as 200 W. Then the copper loss at full load is *

Mark only one oval.

- 800 W
- 200 W
- 100 W
- 400 W

12. The average emf per turn in a transformer is *

Mark only one oval.

- $4f\phi_m$
- $4.44 f\phi_m$
- $2f\phi_m$
- $f\phi_m$

13. The flux in the transformer core is *

Mark only one oval.

- rotating
- partly rotating
- partly alternating
- purely alternating

14. A transformer works on the principle of *

Mark only one oval.

- Faraday's law
- mutual induction
- ferrari
- superposition

15. For a 250/25 V transformer having 1 kVA rating, the full load primary current is *

Mark only one oval.

- 40 A
- 4A
- 0.4 A
- 0.04 A
- Option 5

16. The value of flux used in the emf equation of a transformer is *

Mark only one oval.

- RMS
- average
- maximum
- instantaneous

17. For a 50 Hz transformer, the primary turns are 100 and maximum flux in the core is 0.08 Wb then the primary induced emf is *

Mark only one oval.

- 1856 V
- 1276 V
- 176 V
- 1776 V

18. A transformer has 200 W iron loss at full load. The iron loss at half full load is *

Mark only one oval.

- 100 W
- 200 W
- 400 W
- 300 W

19. A 250KVA single phase transformer has iron loss is 1.8KW and full load copper loss is 2000W. calculate 1)KVA load at maximum efficiency condition 2) Maximum efficiency at 0.8 power factor *

Mark only one oval.

- 237.17KVA, 98.15%
- 247.17KVA, 95.25%
- 257.17KVA, 96.25%
- 267.17KVA, 97.25%

This content is neither created nor endorsed by Google.

Google Forms

