



CMR INSTITUTE OF TECHNOLOGY		USN									
Internal Assessment Test –III											
Sub:	BASIC ELECTRICAL ENGINEERING							Code:	21ELE23		
Date:	30 /8/2022	Duration:	90 mins	Max Marks:	50	Sem:	2nd sem	Branch:	EE/EC/AI/AD		
Answer any FIVE FULL Questions											
								Marks	OBE		
									CO	RBT	
1	What is earthing? Why earthing is required?. With neat diagram explain the different types of earthing.							[10]	CO5	L2	
2 a)	With a neat diagram, describe the main parts of synchronous generator with their functions.							[5]	CO4	L2	
2b)	The stator of a 3-phase, 8-pole, 750 rpm alternator has 72 slots, each of which contains 10 conductors. Calculate the rms value of the emf per phase if flux per pole is 0.1 wb sinusoidally distributed. Assume the coil is 5/6 th full pitched and winding distribution factor of 0.96.							[5]	CO4	L3	
3 a)	With a neat diagram explain how a rotating magnetic field is produced in the air gap of ac machine when a three phase supply is given.							[5]	CO4	L2	
3 b)	A 4 pole, 3300 V, 50Hz induction motor runs at rated frequency and voltage. The frequency of the rotor currents is 2.5 Hz. Find slip and running speed							[5]	CO4	L3	
4 a)	Derive an expression for EMF induced in a single phase transformer. Compare between shell and core type transformers.							[5]	CO3	L1	
4b)	List different types of loss in a transformer and explain each one in brief.							[5]	CO3	L2	

CMR INSTITUTE OF TECHNOLOGY		USN									
Internal Assessment Test –III											
Sub:	BASIC ELECTRICAL ENGINEERING							Code:	21ELE23		
Date:	30 /8/2022	Duration:	90 mins	Max Marks:	50	Sem:	2nd sem	Branch:	EE/EC/AI/AD		
Answer any FIVE FULL Questions											
								Marks	OBE		
									CO	RBT	
1	What is earthing? Why earthing is required?. With neat diagram explain the different types of earthing.							[10]	CO5	L2	
2 a)	With a neat diagram, describe the main parts of synchronous generator with their functions.							[5]	CO4	L2	
2b)	The stator of a 3-phase, 8-pole, 750 rpm alternator has 72 slots, each of which contains 10 conductors. Calculate the rms value of the emf per phase if flux per pole is 0.1 wb sinusoidally distributed. Assume the coil is 5/6 th full pitched and winding distribution factor of 0.96.							[5]	CO4	L3	
3 a)	With a neat diagram explain how a rotating magnetic field is produced in the air gap of ac machine when a three phase supply is given.							[5]	CO4	L2	
3 b)	A 4 pole, 3300 V, 50Hz induction motor runs at rated frequency and voltage. The frequency of the rotor currents is 2.5 Hz. Find slip and running speed							[5]	CO4	L3	
4 a)	Derive an expression for EMF induced in a single phase transformer. Compare between shell and core type transformers.							[5]	CO3	L1	
4b)	List different types of loss in a transformer and explain each one in brief.							[5]	CO3	L2	

5 a)	What will happen if a transformer is supplied with DC input. Justify your answer.	[4]	CO3	L2
5 b)	A 40KVA, 1-phase transformer has core loss of 450 W and full load copper loss 850 W. If the power factor of the load is 0.8. Calculate (i) Full load efficiency (ii) Total losses at half load (iii) Maximum efficiency at unity power factor (iv) Load for maximum efficiency	[6]	CO3	L3
6 a)	A 50KVA, single phase transformer has primary and secondary turns of 300 and 20 respectively. The primary winding is connected to a 2200V, 50 Hz supply. (i) Calculate no load secondary voltage (ii) Approximate values of primary and secondary currents on full load (iii) Maximum value of flux density	[6]	CO3	L3
6b)	Explain the construction of a single phase transformer with a neat diagram.	[4]	CO3	L2
7 a)	Derive an expression for frequency of induced emf in case of 3 phase alternator	[4]	CO4	L2
7 b)	A 3 phase induction motor with 4 poles is supplied from an alternator having 6 poles and running at 1000 rpm. Calculate (i) Synchronous speed of induction motor (ii) Its speed when slip is 0.04 (iii) Frequency of rotor emf when speed is 600rpm	[6]	CO4	L3

5 a)	What will happen if a transformer is supplied with DC input. Justify your answer.	[4]	CO3	L2
5 b)	A 40KVA, 1-phase transformer has core loss of 450 W and full load copper loss 850 W. If the power factor of the load is 0.8. Calculate (i) Full load efficiency (ii) Total losses at half load (iii) Maximum efficiency at unity power factor (iv) Load for maximum efficiency	[6]	CO3	L3
6 a)	A 50KVA, single phase transformer has primary and secondary turns of 300 and 20 respectively. The primary winding is connected to a 2200V, 50 Hz supply. (i) Calculate no load secondary voltage (ii) Approximate values of primary and secondary currents on full load (iii) Maximum value of flux density	[6]	CO3	L3
6b)	Explain the construction of a single phase transformer with a neat diagram.	[4]	CO3	L2
7 a)	Derive an expression for frequency of induced emf in case of 3 phase alternator	[4]	CO4	L2
7 b)	A 3 phase induction motor with 4 poles is supplied from an alternator having 6 poles and running at 1000 rpm. Calculate (i) Synchronous speed of induction motor (ii) Its speed when slip is 0.04 (iii) Frequency of rotor emf when speed is 600rpm	[6]	CO4	L3

$$kVA = V \cdot I = 40 \times 10^3 \text{ VA}$$

5b. $P_i, P_{\text{core loss}} = 450 \text{ W} (P_i)$

$P_{cu}, P_{\text{copper loss}} = 850 \text{ W} (\text{Full load})$

$p.f = 0.8.$

(i) Full load efficiency, $\eta = \frac{\text{o/p}}{\text{i/p}} = \frac{V I \cos \phi}{V I \cos \phi + P_i + P_{cu}}$

$$\eta = \left(\frac{40 \times 10^3 \times 0.8}{40 \times 10^3 \times 0.8 \times 450 + 850} \right) \times 100$$

$$= \frac{32000}{32000 + 450 + 850} \times 100$$

$$= 96.04\%$$

$$= \underline{\underline{96.04\%}}$$

(ii) Total losses at half load

$$\text{Total Losses} = P_i + P_{cu}(\text{half load})$$

$$= 450 + x^2 \cdot P_{cu}$$

$$= 450 + (0.5)^2 \times 850$$

$$= 662.5 \text{ W}$$

$$x = \frac{1}{2} = 0.5.$$

(iii) Maximum efficiency at 1/2 load

Load for Maximum efficiency

$$P_i = P_{cu}(\text{at } x \text{ load})$$

$$P_i = x^2 \cdot P_{cu}$$

$$450 = (x)^2 \cdot 850$$

$$\Rightarrow x = \sqrt{\frac{450}{850}}$$

$$x = \underline{\underline{0.7276}}$$

(ii) Max efficiency at UPF
 Maximum efficiency occurs at $x = 0.7276$.

$$p.f = 1$$

$P_{cu(x)}$ = Copper loss. (At Max η)

$$\Rightarrow \eta = \frac{40 \times 10^3 \times 1}{40 \times 10^3 \times 1 + 450 + 450}$$

$$= \underline{\underline{97.79\%}}$$

6 a) $V \cdot I = 50 \times 10^3 \text{ VA} \Rightarrow \text{A} \cdot \text{V} =$

$$N_s = 20$$

$$N_p = 300$$

$$V_p = 2200 \text{ V}$$

$$f = 50 \text{ Hz}$$

i) $\frac{N_s}{N_p} = \frac{V_s}{V_p}$

$$\Rightarrow V_s =$$

$$V_s = V_p \cdot \frac{N_s}{N_p} = \frac{2200 \times 20}{300} = \underline{\underline{146.66 \text{ V}}}$$

(ii) $V_s I_s = V_p I_p$

$$\Rightarrow \underline{\underline{146.66 \cdot I_s}}$$

Also, $V_p I_p = 50 \times 10^3$

$$I_p = \frac{50 \times 10^3}{V_p} = \frac{50000}{2200} = \underline{\underline{22.72 \text{ A}}}$$

$$\text{Also, } I_s = \frac{50 \times 10^3}{V_s} = \frac{50000}{146.66} = \underline{\underline{340.924 \text{ A}}}$$

(ii) Maximum flux density.

~~Let~~ EMF at primary side, $V_p = E_p = 2200$.

$$\Rightarrow V_p = 4.44 f \phi_m N_p$$

$$\Rightarrow 2200 = 4.44 \times 50 \times \phi_m \times 300$$

$$\phi_m = \underline{\underline{0.0330 \text{ Wb.}}}$$

Assume area = ~~60 cm²~~ 60 cm^2


$$\Rightarrow \text{Flux density} = \phi \cdot \frac{\phi_m}{\text{Area}} = \frac{0.0330}{\cancel{60} \times 10^{-4}}$$

$$= \underline{\underline{5.5 \text{ Wb/m}^2}} = \underline{\underline{5.5 \text{ Wb/m}^2}}$$

I) Electromagnetism: -

- Assume a Conductor is Carrying Current as shown in fig.

- Wrap your fingers around the Conductor in direction of Current, thumb points in the direction of magnetic field.



II) Electromagnetic Induction: -

a) Self-Induction: - Whenever there is a change in the flux linked with a Coil, an emf is induced, if the emf is induced in the same circuit, then it is "Self Induction".

b) Mutual Induction: - Assume there are 2 Coils placed nearer to each other

- first Coil carries some current I , which give rise to a magnetic field B .

- Since the 2 coils are nearer some flux lines will link with the 2nd coil also.

- Now as current changes, $d\phi$ linked with the 2nd coil also changes, hence an emf induced in the second coil also. } pre-requisite.

- when $N_2 > N_1 \rightarrow$ step-up transformer.

- when $N_1 > N_2 \rightarrow$ step-down transformer.

Effect of slip on Rotor frequency:-

→ In Case of I.M, the speed of rotating magnetic field is, $N_s = \frac{120f}{P}$.

→ At start, when $N=0$, $s=1$ and stationary rotor has maximum relative speed with respect to RMF. Hence maximum emf gets induced in the rotor at start.

→ The frequency of this induced emf at start is same as that of supply frequency.

→ As motor actually rotates with speed N , the relative speed of rotor wrt RMF decreases and becomes equal to slip speed $N_s - N$.

→ As the induced emf in rotor depends upon rate of change of flux, i.e., relative speed $N_s - N$, it decreases and so as its frequency also decreases.

→ If f_r is the frequency of rotor, induced emf and rotor currents, in running condition at slip speed $(N_s - N)$ then there exists a fixed relation between $(N_s - N)$, f_r and P .

$$(N_s - N) = \frac{120f_r}{P}$$

$P = \text{Rotor + Stator poles.}$

Dividing with N_s on both sides

$$\frac{N_s - N}{N_s} = \frac{120f_r}{PN_s}$$

$$\frac{N_s - N}{N_s} = \frac{120f_r}{P \left(\frac{120f}{P} \right)} = \frac{f_r}{f}$$


$$s = \frac{f_r}{f}$$

$$f_r = s f$$

→ The frequency of rotor induced emf in running condition (f_r) is slip times the supply frequency (f).

is a part of Induction Motor:

7b)



IM
P = 4.

The frequency of alternator and IM stator is the same

Alternator
P = 6.

$N_s = 1000 \text{ rpm}$

$$f_s = \frac{P \cdot N_s}{120}$$

$$= \frac{6 \times 1000}{120} = 50 \text{ Hz}$$

$$\Rightarrow f_s = 50 \text{ Hz}$$

(i)
$$N_s = \frac{120 f_s}{P} = \frac{120 \times 50}{4} = 1500 \text{ rpm}$$

(ii) N_r at slip. = 0.04.

$$\begin{aligned} N_s &= N_s (1 - s) \\ &= 1500 (1 - 0.04) \\ &= \underline{\underline{1440 \text{ rpm}}} \end{aligned}$$

(iii)
$$f_r = s \cdot f_s = \left(\frac{N_s - N_r}{N_s} \right) f_s \quad \parallel N_r = 600$$

$$= \left(\frac{1500 - 600}{1500} \right) 50$$

$$f_r = \underline{\underline{30 \text{ Hz}}}$$