

Fifth Semester B.E. Degree Examination, Aug./Sept.2020 **Manufacturing Process - III**

0110	Tim	è/3	hrs. Max. M	arks:100
Ipract	No	te:	Answer any FIVE full questions, selecting atleast TWO questions from e	ach part.
E CONTRACTOR OF THE CONTRACTOR				Annance and a
reated as	1	a.	How are metal forming processes classified? Explain with sketches. Derive an expression to establish the relationship between:	(10 Marks)
ink pages.), will be t		о. С.	i) Conventional stress and True stress ii) Conventional strain and True strain. Differentiate Wrought product and Cast product.	(05 Marks) (05 Marks)
ing bla +8 = 5(2	a.	Explain the effect of the following on metal working process: i) Friction and Lubrication ii) Temperature.	(10 Marks)
nair , 42		h	Explain with a neat sketch, the hydrostatic pressure in metal working.	(05 Marks)
the rer ten eg		c.	Briefly explain how the residual stresses are formed in metal working processes.	(05 Marks)
on wri	3	a.	Derive an expression for forging pressure and load in open die forging by slab	analysis in
lines ions			sliding friction at the interface and draw friction hill.	(10 Marks)
oss		b.	Briefly explain the defects that are seen in forged product.	(04 Marks)
il cr		c.	A rectangular bar of length 200mm, width 100mm and thickness 40mm is of	compressed
gona nd /c			between two flat dies in plane strain condition such that the plane sections remain	n same and
diag or ar			the dimension 200mm does not change. If the yield strength of the work	material is
aw			75N/mm ² and coefficient of friction M = 0.08, determine the minimum average	
ly dr eval			maximum die pressure at the beginning of compression.	(06 Marks)
sori I to	4	a.	Derive and expression for maximum possible reduction in rolling processes.	(04 Marks)
npul	•	b.	With a neat sketch, explain different types of rolling mill arrangement.	(10 Marks)
con		c.	A strip is given 20% reduction in thickness by rolling operation. If its final t	hickness is
ers, atior			5mm and roll radius is 500mm, determine the position of the neutral plane. Take	$\mu = 0.2$ and
nsw			assume the plane strain condition for rolling.	(06 Marks)
ur al dent			PART - B	
g yo of i	5		Explain with a neat sketch, tube drawing process.	(06 Marks)
eting ling	3	a. h	Derive an expression for drawing load by slab analysis.	(08 Marks)
nple		c.	Explain Optimal cone angle and dead zone formation in drawing.	(06 Marks)
y re		٥.	Explain Optimal cone angle and acad zone formation in also, in-g.	
Or	6	a.	With neat sketches, explain briefly direct and indirect extrusion.	(06 Marks)
.1.			Explain the following: i) Defects in extrusion ii) Lubrication in extrusion.	
Important Note : 1.		C.	Explain any four variables influencing extrusion process.	(04 Marks)
nt 7	7	а	Draw neat sketches of Compound die and Progressive die. Briefly explain their	principle of
orta	,	u.	working.	(10 Marks)
duıj		b	Explain briefly the rubber forming process with respect to sheet metal forming.	(05 Marks)
,			Explain the term limiting draw ratio as applied to deep drawing.	(05 Marks)
	0			(08 Marks)
	8	a. L	Explain the basic steps of powder metallurgy with the help of flow chart. What are the various finishing operation carried out in powder metallurgical pr	
		0.	sintering? Explain each briefly.	(06 Marks)
		•	Explain with neat sketch, the principle of working, advantages and app	
		C.	explain with neat sketch, the principle of working, advantages and app	(06 Marks)

explosive forming.

(06 Marks)