USN

Seventh Semester B.E. Degree Examination, Dec.2019/Jan.2020 **High Voltage Engineering**

ANG LONE

Max. Marks:100

-			Note: Answer any FIVE full questions, selecting	
ų;			atleast TWO questions from each part.	
Any revealing of identification, appeal to evaluator and /or equations written eg, 42+8 = 50, will be treated as maipfaction.			PART – A	
IIIa	1	a.	Explain the need for generation of very high voltages in the laboratory.	(06 Marks)
	_	b.	What are the industrial applications of high voltages?	(08 Marks)
		c.	Explain Townsand's theory of gas breakdown. Derive equation of current growth.	
í B				(06 Marks)
	2	a.	Explain the streamer theory of breakdown in air and obtain the expression for small	allest value
Ŝ	_		of α .	(10 Marks)
		b.	Explain the various theories that explain breakdown in commercial liquid dielectri	ics.
				(10 Marks)
ì				
	3	a.	Write short notes on: (ii) Thormal breakdown	(14 Marks)
		L	(i) Electromechanical breakdown (ii) Thermal breakdown Explain time lags for breakdown of gas.	(06 Marks)
		b.	Explain time lags for breakdown of gas.	(**************************************
-	4		Write short notes on:	
	7		(i) Cascaded transformer	
			(ii) Resonant transformer = 4FFB 2020	v
			(iii) Tesla coil.	(20 Marks)
			A Control of the Cont	
			PART – B	
3	5	a.	Explain how impulse voltages are generated in laboratory using MARX circuit.	(10 Marks)
1	3	b.	What is a trigatron gap? Explain its functions and operation.	(10 Marks)
				and the second s
	6	a.	With a neat sketch, explain the construction and working principle of electrostatic	voltmeter.
			Bring out their advantages and disadvantages.	(10 Marks)
		b,	Explain in detail about the sphere gap measurements and mention the factors at	(10 Marks)
p D		E.	measurements.	(10 Marks)
	-	_	Explain the simple and accurate method of measuring peak values of ac	voltages as
	7	a.	suggested by Chuff and Fortescue method.	(10 Marks)
		h	With the help of a neat sketch, explain the construction and principle of his	
		b.	Schering bridge used for dielectric loss angle measurements. Derive the expression	n used.
			Soliding bridge about in the magnitude and in the magnitude and in the magnitude about in t	(10 Marks)
	8	a.	Explain with a neat diagram, the procedure for impulse testing of power transform	ner. (08 Marks)
		1 _c	Write short notes on:	(00 Marks)
		b.		
			(i) Testing of cables.	(12 Marks)
			(II) I coming of cacies.	