

- c. Give the sources of effluents from a cement manufacturing process. (05 Marks)
- 8 a. Draw a neat flow diagram for the manufacture of paper and pulp and give a treatment strategy for the combined waste. (10 Marks)
- b. Give the strategy of treating using bacteria for antibiotic waste from a pharmaceutical industry. (05 Marks)
- c. Effective maintenance of food to micro – organism ratio is essential for treating industrial wastes. Explain. (05 Marks)
